

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

Copy for Books

LAND CORNER RECORD


OAKLAND COUNTY
T 3N R 8E

DESCRIPTION OF CORNER 1/8 POST IN THE CENTER OF NE 1/4 OF SEC 27

CORNER MONUMENT MON. BOX IN E OXBOW LAKE ROAD

DATE MONUMENT ~~REGISTERED~~ WITNESSED APRIL 1971

WITNESSES TO CORNER..... N 53°W 61.80' POWER PILE



N 83°E 77.45' 12" OAK

N 32°E 60.45' NORTH END OF 24" CONC. CURVE

AND N 20°W 80.4' SOUTH END 12' CONC. CURVE

CIRCLE CORNER REGISTERED 26' SOUTH OF CENTERLINE OF MILL RD AS EXISTING

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

SURVEYOR'S SEAL

DISTRIBUTION: SIGNED _____ DATE _____
REGISTERED LAND SURVEYOR

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68