File

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

			5 ^{ec} _
FOR CORNERS OF -: LO	CATED IN-:	CORNER CODE NUMBER	1 12 /2 Q
1. PUBLIC LAND SURVEY T.	3 N. R. 8 E.	<u> 2-J</u>	16 10 C
2. PROPERTY CONTROLL- ING IN SECTION——,T	3 N. 8 E.		ON ON O
3. MISCELLANEOUS PROPERTY IN SECTION, T			CALANDER CO QUE
4. LOT NO , RECORDED	PLAT		\
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on 1922, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1923, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original monument and accessories and/or subsequent restoration: FOUND 3/4 "IPON PIPE 2" ABOVE GROUND FROM WITNESSES FURNISHED BY DETROIT EDISON COMPANY			
B. Description of corner evidence for	ound and/or method app	lied in restoring or re-estab	lishing corner:
C. Description of monument for cor \$ 44° W	7' 8"0 9" 7" 7.	AK WIH OAK I, OAK AK	nting the position of the corner:
SIGNED BY		DATE	
SURVEYOR'S MICHIGAN REGISTRATION NO (SEAL)			
FOR STATE AND UNITED STATES		_	
APPROVED AND SIGNED BY	MICHIGÂN REGISTERED LAN	DATE	(SEAL)