MAY 24 2000

LIBER 21119 601

SECTION

LAND CORNER RECORDA Filing Requirement of Act	74, Mich. P.A. 1975 DER 21119 PAGE 601 \$9.00 MISC RECORDING
For corners in	\$2.00 REHONUMENTATION 02/18/2000 02:36:27 P.H. RECEIPT# 14203
Oakland Located in: Corner Code #	PAID RECORDED - DAKLAND COUNTY G. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS
(county) Rese Township	
Waterford	
1. Public Land Survey T <u>3N R9E E-13 </u>	
T R	- 12. 14 Jn
T R	- LEFT A THE COLD INVENTAL BURNESH AND
2. Property Controlling S T R	1
2. Property Controlling S T R	Register of Deeds Stamp & File Number
Property in Sec. STR	
4. Lot No, Recorded Plat	ABCDEFGHIJKL
5. Private Claims	2 1 1 1 1 1 1 1 1
	3
I, <u>Joseph C. Kapeiczak</u> , in a field survey on <u>March 22, 1999</u> , do he requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentione	d in lines 1 and 2 above 4 7 - 1 - 1 - 10 - 11 - 1
were in conformance with regulations and rules therefore as required in the	surrent manual of survey
instructions of the United States Department of the Interior, Bureau of Lat decree of a Court of Law and/or that the corner points mentioned in lines 3	4 and 5 above were in 6 18 17 16 15 14
conformance with the rules of the Michigan Board of Land Surveyors or by	a Decree of a Court of 7
Law; established, re-established, monumented, re-monumented, recover below:	ed, found as expressed 8 19 20 21 22 23 2
	□
A. Description of original monument and accessories and/or subse	ruent restoration 10 30 28 28 27 26 2
A. Description of original monument and accessories and/or subse	11
Set post in 1816 G.L.O. Survey. There are two LCRC's recorded at Oakland County; Patterson 1 Kapelczak 1991.	990 and 12 31 32 33 34 35 3
B. Description of corner evidence found and/or method applied in re	estoring or reestablishing corner.
Recovered concrete monument with Oakland County Remonum at this location. This corner lies 21.46' west of E-1 West Bloomf found in Pilgrim Hills Subdivision #2.	entation Brass Cap stamped #31606 ield Township and was validated with monumentation
Recovered Witnesses:	į
S 25°E 34.17' PK nail east side 12" Cherry. S 85°E 25.24' PK nail south side base 24"/10" Oak. South 35.83' PK nail with OCRT # 31606 in west side 16" Oak.	
C. Description of monument for corner and accessories established	to perpetuate locating the position of the corner:
Recovered concrete monument with Oakland County Remonum	entation Brass Cap stamped #31606.
Set Witnesses:	2p
North 2.94' set Mag nail with OCRT #24598 west side Twin 34" S 25°E 34.17' set Mag nail with OCRT #24598 east side 12" Che S 85°E 25.24' Mag nail with OCRT #24598 south side Twin 24"/ South 35.83' PK nail with OCRT #24598 #31606 west side 16" ON 87°22'19"E 21.46' found concrete monument E-1 West Bloom	erry. 10" Oak. Oak. OF Months
-	KAPELCZAK PROFESSIONAL SURVEYOR NO. 24598
Signed by July C. Kakelezak	Date 12/22/99
Surveyor's Michigan License No. 24598	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971