SURVEY & REMONUMENTATION

LIBER 15292 PC 374

Mar 1595041986

	[BRITOCOCION =		A & 61***** 3
MAY =	1 1995 LAND CORNER RECORDATION CERT	IFICATE OK - T. S	imit
	Filing Requirement of Act 74, Mich. I	A. 1970 7.00 NISC RECORDING	CH6 - IN HOUSE
OAKLAND COMN	ISSION Corner Code ##	\$ 2.00 REMON CHG - IN 15 MAR 95 8:09 A.M.	
Public Land Survey	T3_N_R 9 E	PAID RECORDED LYNN D. ALLEN, CLERK/R Compliance w ACT 345, P.A.	- OAKLAND COUNTY EGISTER OF DEEDS ith 1990
 Property Controlling in Section Miscellaneous Property in Sec. 	T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R R S T R	APPROVED ON: 12 · 30 OAKLAND COUNTY REMO PEER GROUP CON Register of Deeds Stamp	NUMENTATION IMITTEE
4. Lot No, Re	ecorded Plat	ABCDEF	внізкі
do hereby certify that under requirement in and 2 above were in current manual of survey instruct Management or by a decree of a cabove were in conformance with Court of Law; established, re expressed below:	in a field survey on <u>NOVEMBER 26</u> , 19 94. Direments of P.A. 74, Michigan P.A. of 1970, the corner points men conformance with regulations and rules therefore as required ctions of the United States Department of the Interior, Bureau of Court of Law and/or that the corner points mentioned in lines 3, 4 of the rules of the Michigan Board of Land Surveyors or by a Decrestablished, monumented, re-monumented, recovered, four rules, all in the same town and range, may be recorded.	ioned in the Land 7 and 5 8 19 20 21 and as 10 30 29 28	-10 -11 -12 -13 -15 -14 -13 -22 -23 -24 -27 -26 -25
	nonument and accessories and/or subsequent restoration	13	
1817 L	TEEL POST .C.R.C. . 7886 P. 255 ILLIAMS, 1980		The state of the s
,	idence found and/or method applied in restoring or rees		ITH
	THE WEST. IT APPEARS THE FENCE WAS INSTA F*IED THE FENCE POST WITH THE WITNESSES		
IN LIBER 7886, P.	AGE 255.	A A A C C C C C C C C C C C C C C C C C	THOMAS M. SMITH LAND SURVEYOR NO. 31606
C Description of manumen	it for comer and accessories established to perpetuate I	ocating the position of the corne	SL: NAME WHEN SOME
I-5: I LEFT THE WEST 86.22' to S 30 W. 78.81' to N 70 W. 77.32' to S 40 E. 19.60' to	FENCE POST AS THE CORNER. NO CAP WAS SETTEMON tag N. side 24" box elder. most easterly foundation corner house remon tag S. side 20" box elder. remon tag N.E. side 6" poplar. ATION IS ACCEPTED BY ME AND IS GENERALLY EVIDENCE OF THE ORIGINAL CORNER.	·•	
	w Number		
Signed by		ECEMBER 19, 1994	
Surveyor's Michigan License	No. 31606	FORM APPROVED BY MICHIGAN STATE BOARD OF	LAND SURVEYORS, JAN. 28, 1