SURVEY & REMONUMENTATION

118ER 15292 pc 368

LAND CORNER RECORDATION CERTIFICATE OK - T SMITH MAY - 1 1995

	Filing Requirement of Act 74, Mich. P.A. 1970			
Fo	OAKLAND	OMMISSION Located In: WATERFORD Corner	\$ 7.00 MISC RECORDING CHG - IN HOUSE \$ 2.00 REMON CHG - IN HOUSE	
	(County)		15 MAR 95 8:08 A.M. RECEIPT# 8B	
1.	Public Land Survey	T R	LYNN D. ALLEN, CLERK/REGISTER OF DEEDS Compliance with	
		T R		
2.	Property Controllin in Section	g S T R S T R	OAKLAND COUNTY REMONUMENTATION	
3.	Miscellaneous Property in Sec.	S T R S T R	Register of Deeds Stamp & File Number	
4.	Lot No	, Recorded Plat	A B C D E F G H I J K L	

SMITH , in a field survey on . NOVEMBER 26 THOMAS M. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

POST, G.L.O.


BRASS DISC IN MON.

1817

L.C.R.C.

L. 7326 P. 726

LOHFF, 1978



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I FOUND A BRASS DISK IN THE ASPHALT OF CASS ELIZABETH LAKE ROAD & PARKWAY.

I VERIFIED THE CORNER FROM THE L.C.R.C. BY LOHFF. I MEASURED SOUTH

TO I-13 AND CLOSELY FIT THE MENIWATER SUBDIVISION DIMENSION.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-12: I LEFT THE BRASS DISK ON TOP OF A PIPE IN A NEW MONUMENT BOX.

42.92' to most easterly corner C.B. frame. S 45 E.

S 45 W. 114.75' to remon tag S. side 6" box elder.

30.60' to remon tag E. side wood sign post. N 10 W.

N 10 E. 105.90' to top center of south bolt in conc. base.

THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL SERVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE ORIGINAL CORNER.

Date DECEMBER 19, 1994 Signed by 31606 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 Surveyor's Michigan License No. REVISED MAY 14, 1975

REVISED JAN., 1963