

MAY 24 2000

For corners in

···· 20657 322

ON CERTIFICATE

374943

SECTION	LAND CORNER RECORDATI
	Eiling Paguiroment of Act 7/

4, Mich. P.A. 1970 LIBER 20657 PAGE

9.00 HISC RECORDING	•	
2.00 REMONUMENTATION		
	RECEIPT#	88306
AID RECORDED - OAKLAN	D COUNTY	AC
ATTITION CADDELL. CLERK	(/REGISTER	OF DEEDS

355

Oakland (county)	Located In: Comer Code # Rose Township	PAID RECORDED - ORKLAND COUNTY G. WILLIAM CADDELL, CLERK/REGISTER OF DEE
Property Controlling S	T4N R7E E-7  T R	Compliance with ACT 345, P.A. 1990  APPROVED ON: 4-21-99 JJ  PAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE  Register of Deeds Stamp & File Number
<del>\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ </del>	ded Plat	
i, <u>Joseph C. Kapelczak</u> , in a fie requirements of P.A. 74, Michigan P were in conformance with regulation instructions of the United States D decree of a Court of Law and/or the conformance with the rules of the	old survey on October 7, 1998, do hereby certify 2A of 1970, the comer points mentioned in lines 1 as and rules therefore as required in the current manuscepartment of the Interior, Bureau of Land Manager at the comer points mentioned in lines 3, 4 and 5 at Michigan Board of Land Surveyors or by a Decree of monumented, re-monumented, recovered, found a	that under and 2 above 4 7 8 9 10 11 12 12 13 14 15 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15
NOTE: Not more than 4 cor	mers, all in the same town and range, ma	ay be 10 70 70 77 28

recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Set post in 1816 G.L.O. Survey. There is one LCRC recorded at Oakland County; Ward 1993.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered a 1/2" iron in Fish Lake Road at this location. This location was validated with monumentation recovered along the R.O.W. of Fish Lake Road south of section corner and recovered witnesses in the recorded LCRC's.

\*Recovered Witnesses:

\*N 31°E 57.30' nail west side power pole.

N 31°E 57.30' nail with Oakland County Road Commission tag west side power pole.

\*S 65°E 64.14' nail north side 14" Oak.

S 17°W 47.06' nail east side power pole.

N 24°W 59.84' nail northeast side power pole.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Set 5/8" iron with Oakland County Remonumentation Brass Cap stamped #24598 in gravel road.

Set Witnesses:

\*N 31°E 57.13' Mag nail with OCRT #24598 east side power pole.

\*S 65°E 64.14' OCRT #24598 and Mag nail north side 14" Oak.

\*S 17°W 47.06' OCRT #24598 and Mag nail east side power pole.

\*N 24°W 59.84' OCRT #24598 and Mag nail northeast side power pole.

\*Reused Recovered Witnesses

Surveyor's Michigan License No. 24598



	_	$\cdot$ $\cdot$ $\cdot$ $\cdot$ $\cdot$		`
	ח וו	· // //	, ,	,
	1 K.	1.1/ - 1/	- 1/20	109
Signed by Agela /	- /	selval	Date	77/
- Jane				
<i>i i</i>	//	′ //	· · · · · · · · · · · · · · · · · · ·	•

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1963