

MAY 24 2000 -

Signed by

Surveyor's Michigan License No. '

unik 20657 ± 334

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION 374949 For corners in LIBER 20657 PAGE \$9.00 MISC RECORDING \$2.00 REMONUMENTATION LIBER Comer Code # <u>Oakland</u> Located In: 10/12/1999 08:06:33 A.M. RECEIPT# 88906 PAID RECORDED - DAKLAND COUNTY G. WILLIAM CADDELL, CLERK/REGISTER OF DEED! RECEIPT# 88906 Rose Township (county) 1. Public Land Survey T4N R7E Compliance with ACT 345, P.A. 1990 9-22-55 APPROVED ON: OAKLAND COUNTY REMONUMENTATION
PEER GROUP COMMITTEE 2. Property Controlling S Register of Deeds Stamp & File Number in Section 3. Miscellaneous Property in Sec. ____, Recorded Plat 4, Lot No. ___ 5. Private Claims I, <u>Joseph C. Kapelczak</u>, in a field survey on <u>March 6, 1998</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above s were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above 3 were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a g Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Set post in 1816 G.L.O. Survey. There is one LCRC recorded at Oakland County; Albright 1976. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Recovered a 2" pipe 0.10' north of the township line and 70.58' west of F-13 Holly Township This location was validated with monumentation recovered along Houser Road east of the corner and the south line of T5N., R7E., Holly, Township. Recovered Witnesses: *Due South 19,42' nail with tag #10057/24607 in west side 8" Elm. *S 75°W 21.69' nail with tag #10057/24607 in south side 7" Elm. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" iron with Oakland County Remonumentation Brass Cap stamped #24598. Set Witnesses: *Due South 19.42' Mag nail with OCRT #24598 in west side 8" Elm. *S 75°W 21.69' Mag nail with OCRT #24598 in south side 7" Elm. N 85°E 4.81' Mag nail with OCRT #24598 north side 5" Elm. S 80°E 15.75' Mag nail with OCRT #24598 in north side 8" Elm. JOSEPH C *Reused Recovered Witnesses KAPELCZAK PROFESSIONAL SURVEYOR 24590 PROFESSIONAL ANGESCE SE LE COURTE DE LE COUR Labelcrak

> FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983