

MAY 24 2000

LIBER 20657 376

374970

SECTION

LAND CORNER RECORDATION CERTIFICATE

LIBER 20657 PAGE 376
.00 MISC RECORDING
.00 REMONUMENTATION
10/12/1999 08:06:33 A.M. RECEIPT# 88906
PAID RECORDED - OAKLAND COUNTY
G. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS

For corners in

Table with columns: Oakland (county), Located in: Rose Township, Corner Code #. Rows include Public Land Survey, Property Controlling in Section, and Miscellaneous Property in Sec.

Compliance with ACT 345, P.A. 1990
APPROVED ON: 7-7-99 JK
OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Joseph C. Kapelczak, in a field survey on April 18, 1998, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Grid table with columns A-M and rows 2-13. A dot is marked at the intersection of column H and row 11.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Set post in 1816 G.L.O. Survey. There is one LCRC recorded at Oakland County; Ward 1984.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Recovered a railroad spike in asphalt of Milford Road at this location. This location was validated with monumentation recovered along the R.O.W. of Milford Road along with witnesses of the above-referenced LCRC.

Recovered Witnesses:

- \*S 80°E 52.61' spike with Grant Ward tag south side 24" Oak.
\*S 15°E 87.00' spike with Grant Ward tag west side 24" Hickory.
\*S 35°W 40.56' spike with Grant Ward tag east side triple 8" Oak.
\*S 75°W 31.76' nail north side 24" Oak.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Oakland County Remonumentation Brass Cap stamped #24598 in monument box.

Set Witnesses:

- \*S 80°E 52.61' Mag nail with OCRT #24598 south side 24" Oak.
\*S 15°E 87.00' Mag nail with OCRT #24598 west side 24" Oak.
\*S 35°W 40.56' Mag nail with OCRT #24598 east side triple 8" Oak.
\*S 75°W 31.76' Mag nail with OCRT #24598 north side 24" Oak.

\*Reused Recovered Witnesses



Signed by Joseph C. Kapelczak
Surveyor's Michigan License No. 24598

Date 7/1/99