

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	9 4	none of Aut 14, thioli.	IA IVIV			127	806					
For corners in	,			\$9.00	MISC	3 PAGE RECORDI	NG					
Oakland (county)	Located In: Cor Rose Township					\$2.00 REMONIMENTATION 05/19/2000 10:35:44 A.M. RECEIPT# 36329 PAID RECORDED - OAKLAND COUNTY G. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS						
1. Public Land Survey	T <u>4N</u> R <u>7E</u> J		to the property of the propert	o. WT				/KEGI	SIER O	F DEEDS		
	T R T R		1.		AC	Ompiian T 345, p	ce with	P				
 Property Controlling S_ in Section S_ Miscellaneous S_ Property in Sec. S_ 	T R		APPROVED ON: 5-25. SS JR OAKLAND COUNTY REMONUMENTATION Register of Deeds Stampartier number									
4. Lot No, Re	corded Plat				,							
5. Private Claims	<u> </u>			^	B C	D E	FG	H 1	J K	L M		
	Siele en march	4000		2 -	6	5	· 	· \$ —	-2-	 		
requirements of P.A. 74. Michid	a field survey on <u>February</u> , gan P.A. of 1970, the corner po	ints, mentioned in lines 1 ar	nd 2 ahove	4	ļ	3		10		12		
instructions of the United State	lations and rules therefore as re as Department of the Interior, I	Bureau of Land Manageme	ent or by a				++	+	+			
conformance with the rules of:	or that the corner points mention the Michigan Board of Land St	urvevors or by a Decree of	a Court of	6 — 1		1 7	18-	15	14	{3 		
Law; established, re-establish below:	ed, monumented, re-monument	nted, recovered, found as	expressed	81		20	21	22	23	24		
A Description of original m	onument and passessing			9		 	} 	\Box	1	- -		
	onument and accessories a	and/or subsequent resto	'	° 3		29	28	27	-26-	25		
Set post in 1816 G.L.O.: There are no I CRC's re-	Survey. corded at Oakland County.			22		<u> </u>	<u>†</u> †	<u>†</u> †				
	, and the second se	رمدسر ما المسال الم	1	33		32	33	34	35	36		
reestablishing corner:	dence found and/or method	applied in restoring or										
No monumentation was from I-1 to K-1, being setownship.	recovered at this location. t on the township line betwe	This corner was re-esta en J-13 and l-13. This	blished uti corner as	lizing set is	g a sir s 13.1	gle pro 4' wes	oportic t of J-	nal r 13 Ho	nethod olly	ť		
C. Description of monumen	t for corner and accessorie	s established to perpetu	ate locatir	g the	e posi	tion of	the co	rner:				
Set concrete monument	with Oakland County Remo	onumentation Brass Car	o stamped	#245	598.							
Set Witnesses:												
N 18°W 28.04' Mag nail with OCRT #33138 south side 14" Elm. N 42°E 33.34' 20 Penny nail with OCRT #24598 southeast side 8" Elm. S 33°E 13.28' Mag nail with OCRT #33138 north side 6" Poplar. S 80°W 27.13' Mag nail with OCRT #24598 south face of 2 sawed off power poles.			noles				2p					
West 32.66' J-13 Holly To	ownship.		o .	The Sections	TE OF JOS KAP	ELCZA	Manager And Andrews All Control of the Control of t					
:					de.	1VEYOF No. 14598		The Participant				

PADEESSIONAL

Surveyor's Michigan License No. 24598

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983