# LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

416601

	•	•		4 77	en n		tone.							
For comers in				\$9	BER 2 00 MI 00 RE	SC REC	CORDIN	G	)					
Oakland (county)					16/19	99 08: RECORI	:01:34 )ED -	'A.M. OAKLA	IND C	DUNTY				
1. Public Land Survey	T <u>4N</u> R <u>7E                                   </u>			-			ŕ			J1016		V LL.		
	T R	Compliance with ACT 345, P.A. 1990												
2. Property Controlling S in Section S	T R RE				APPROVED ON: 10-13-95 JR DAKLAND COUNTY REMONUMENTATION									
3. Miscellaneous S Property in Sec. S	T R	Register of Deeds Stamp & File Number												
4. Lot No, Reco	rded PlatSI	ECTION				_								
5. Private Claims				<u>,</u>	BC	D	E F			<u> </u>		~		
o. I made odanio				3		- 5				_2_				
I, Joseph C. Kapelczak, in a fi					<del>}</del> ₋∔	- 8	 9	-   -	0-	_{-1/-		2		
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 abovere in conformance with regulations and rules therefore as required in the current manual survey instructions of the United States Department of the Interior, Bureau of Land Managem or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above.						1				+		$\exists$		
					18	<u>'</u>	16-							
were in conformance with the rules of the Michigan Board of Land Surveyors or by a De Court of Law, established, re-established, monumented, re-monumented, recovered,					9	-20	] 21		2	_23 <u>_</u>	<b>-</b>	4		
expressed below:	Raphshed, Monamented, 16-11	ionamentea, recoverca,	, loulid 43	9	$\vdash$	+	-		-	+	$\left  \cdot \right $	_		
A. Description of original monument and accessories and/or subsequent restore			ation:	<b>^</b>	3 <sup>1</sup> 0	2 <sup>1</sup> 9	2 <sup>1</sup> 8	2	7 	2'8 	+2 	5		
Set post in 1816 G.L.O. Su	Urvev			2	31	-32	33	3	4	<b>-35</b> -		6-		
There are no LCRC's recor			1	3 L						l				
B. Description of corner evide	ence found and/or method a	applied in restoring or	reestablish	ning	corne	r:								
Recovered a ½" iron at this between corners K-8 and K	s location. This location wa <-7.	s validated with monu	ımentation	rec	overe	d alo	ng th	e se	ction	ı line				
C. Description of monument f	for corner and accessories e	established to perpetu	ate locatín	g the	e posi	ition	of the	con	ner:					
Set concrete monument wi	ith Oakland County Remon	umentation Brass Cap	stamped	#24	598.									
Set Witnesses:														
N 45°E 62.51' Mag nail wit S 48°E 60.70' Mag nail wit N 85°E 61.59' Mag nail wit N 02°E 20.78' Mag nail wit	10" Oak. 30" Oak.						2)	)						
		<b></b>						12	ĸ.					
						lila.								
					******	-74 <b>698\$</b> }	Da.							



Signed by Kuph C. Kafelleyak
Surveyor's Michigan License No. 24598

Date /1/12/99

### **JANUARY 25, 1999**

#### **OAKLAND COUNTY REMONUMENTATION**

**CORNER K-8** 

Dossier for: The 1/4 corner common to Sections 23 & 24, T.4N R.7E. Rose Township, Oakland County, Michigan.

#### G.L.O. Survey History

Rose Township was originally surveyed by Holmes, Fletcher & Wampler D.S. 1816 and 1823. The township was subdivided into sections with closing corners set on North and West Township lines. Posts were originally set as noted on enclosed Oakland County Land Recordation Certificate.

# **Existing Field Evidence**

There are no LCRC's recorded at Oakland County.

Recovered a ½" iron at this location. This location was validated with monumentation recovered along the section line between corners K-8 and K-7.

# Recent Corner Record, Survey and Measurement Evidence

K-8 to K-7

2627,51' meas.

2640.00' rec. G.L.O.

2629.08' rec. Sidwell Section 23 2630.71' rec. Sidwell Section 24

K-8 to K-9

2635.78' meas.

2640.00' rec. G.L.O.

Note: All measured distances represent grid distance SPC MI South Zone.

# Surveyor's Recommendation

I, therefore recommend that the Oakland County Peer Group accept this corner as the best position of original corner in regard to evidence found.

SURVEY &

MAR 21 2000

**SECTION**