

MAY 2 4 2000

## SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

127810

'			15/810								
For corners in	•			LIBER \$9.00		3 PAG RECORD		19			
Cakland (county)	Located In: Rose Township	Corner Code #		\$2.00 05/19/ PAID	REMON 2000' REC	UMENTA 10:35: ORDED	TION 44 A.M - OAKL	and co	HINTY		
1. Public Land Survey	T <u>4N</u> R7 <u>E</u> T R	M-2		OF #21	-CATIRE	CADDELI	ig ULE	KK/KE	3191FK	Ur D	ŁŁDS
•		Complisace ACT 345, P.A.						١			
2. Property Controlling S T R					ΩN	F.4.	55	۳۲			
in Section S T R Ragister  3. Miscellaneous S T R Ragister						TY REA	IONUI MMLI	MENT.	ATION	i	
Property in Sec. S	TR		Register		cas is						
4. Lot No. , Reco	udo d Diot		•				1				
4. Lot No, Reco	rded Plat			A i	3 C	0 E	F G	H	1 4	K L	. M
5. Private Claims	<u> </u>			2 - 6		5—	-   -	_ \$	    	╀-	<b>{</b> →
I, Joseph C. Kapelczak, in a field sur	vey on <u>August 5, 1998.</u>	do hereby certify that under	requirements of P.A.	3		+	+	-+-	$\vdash$	十	H
74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States						3	- è I	-10- 	<b>├</b> ?'-	†	(2 
Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land						17	18				
Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented,						-	11	<del>-</del>		4	
recovered, found as expressed below	v:			8-1	-	20-	-21	22	23-	<del>- -</del>	4-
A. Description of original monu	ment and accessories	and/or subsequent restor		اداد	~	++	+	+	<del>      -</del>	1	H
Set post in 1816 G.L.O. Surv	ev.	•		10 <u>3</u> (	<b>)</b>	29	-28	27 	-28-	1-	25  
There is one LCRC recorded	at Oakland County;	Ward 1993.		2 _3		32	33	_34_	35		8
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:							<u> </u>	<u> </u>	LÏ		Ш
No monumentation was recording the corner in 1993, and that is M-1 and A-2 of Springfield T	s to set the corner hal	f way between M-1 and N	A-3 on the line betw	reen				CRC e	stablis	hed	
Recovered Witnesses:				•							
S 34°E 30.05' nail with tag #2 N 53°W 24.64' nail with tag #2 S 10°E 72.78' nail with tag #2	#22445 southwest sid	e 16" Oak.									
C. Description of monument for	corner and accessorie	es established to perpetua	te locating the posit	tion of	the co	orner:	; ;	0	v)		
Found iron with Oakland Cou	inty Remonumentation	on Brass Cap stamped #22	2445 in gravel road.					1 /	Y		
Set Witnesses:							:	Y			
S 34°E 30.07' Mag nail with 6 S 32°W 35.73' Mag nail with N 53°W 25.56' Mag nail with S 12°E 72.99' Mag nail with 6	OCRT #24598 south OCRT #24598 south	least side 8" Oak. 1 side 16" Oak.	Moon Wall of the Control of the Cont	FJOS KAP	SEPHELOS	OMONO CHO C. S					
				rhuh IUB I	RVEYO	inal §	W dr				

Date 5/15/2000

Signed by

Surveyor's Michigan License No. 24598

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 DEVISED IAM 1082