

MAY 24 2000

UBIR 19832 PC 755

SECTION	LAND CORNER RECORDATION CERT	IFICATE 128321
For corners in Oakland (County) Located	Filing Requirement of Act 74, Mich. P.	\$9.00 MISC RECORDING \$2.00 REMONUMENTATION 04/14/1999 01:54:01 P.M. RECEIPT# 1 PAID RECORDED - BAKLAND CRINTY
1. Public Land Survey	T ^{4N} R 8E 1-7 T R	G. WILLIAM CADDELL, CLERK/REGISTER O Compliance with
2. Property Controlling Sin Section S 3. Miscellaneous S Property in Sec. S	TR	ACT 345, P.A. 1990 APPROVED ON: 2-11-59 OAKLAND COUNTY REMONUMENTATIO PEER GROUP COMMITTEE Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat		
5. Private Claims		1 BCDEFGHIJKL
conformance with regulations and rules therefore conformance with regulations and rules therefore united States Department of the Interior, Bureau that the corner points mentioned in lines 3, 4 and Board of Land Surveyors or by a Decree of	curvey on April 8 7, 19 8 do hereby state that up 7, the corner points mentioned in lines 1 and 2 above were 8 as required in the current manual of survey instructions of 9 of Land Management or by a decree of a Court of Lawan 9 do 5 above were in conformance with the rules of the Michi 9 a Court of Law; established, re-established, monumen	e in the 5 17 16 15 14 13
recovered, round as expressed below:	,	8 -19 -20 -21 -22 -23 -24
NOTE: Not more than 2 corners, all in the to on this certificate.	same town and range, may be recorded	9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A. Denedation of attached by		12 - 31 - 32 - 33 - 34 - 35 - 36
	accessories and/or subsequent restoration:	
I-7 Post, per G.L.O. Notes.		
		· · · · · · · · · · · · · · · · · · ·
		4.0
B. Description of corner evidence found a	ind/or method applied in restoring or reestablishing	corner:
I-7 Southwest Corner of Section	on 14, T. 4 N., R. 8 E.	p_
Previously Recorded in L.	15655 P. 272 of Oakland County Records	, ,
(n) Indicates the number of	references that confirms this corner by di	mensional tie.
This corner location is acce as the best available evider	pted by the contractor and is generally acceed the position of the original corner.	cepted by professional surveyors
C. Description of monument for corner and	accessories established to perpetuate locating the Reference to Southerly Reference Monu Set Monument & Remonumentation Ca	ment for I-7, T. 4 N., R. 8 E.,
WARD S 20° W 32.73' Set MAG Nail & Remonumentation Disc in		
SURVEYOR (NO. 22445	West 20.44' Set MAG Nail & I face of 10" Oak.	Remonumentation Disc in North
1100 1100 000	face of 4" Oak.	Remonumentation Disc in North Remonumentation Disc in East
Signed by	face of 16" Pine.	
Surveyor's Michigan License No		ebruary 24, 1999

22445