	LIBER 18129 # 488	i <b>EE</b> 23
	LAND CORNER RECORDATION CERTIFICATE	89
For	Filling Neurit Cinetit Of ACt 74. Millit. P.A. 1370	20
-	Oakland Located In: Corner Code #	<b>=</b>
2.	Public Land Survey  T 4N R 8E M-2  T R 23 FEB 98 11:12 A.M. RECEIPT# 156  PAID RECORDED - OAKLAND COUNT  T R T R TATRON  Property Controlling S T R  IN Section  S T R T R TARRON  APPROVED ON: 1-14-18 GS  OAKLAND COUNTY REMONUMENTATION  PEER GROUP COMMITTEE	Y
	Property in Section S T R R Register of Deeds Stamp & File Number	
4.	Lot No, Recorded Plat A 8 C D E F G H J K	
5.	Private Claims A 8 C D E F G H J K	+
in lig mar Mar 5 al Dec as 6	James J. Scharl, in a field survey on 11–17, 19 97 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned nes 1 and 2 above were in conformance with regulations and rules therefore as required in the current nual of survey instructions of the United States Department of the Interior, Bureau of Land nagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and bove were in conformance with the rules of the Michigan Board of Professional Surveyors or by a cree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found expressed below:	-12
NO	TE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	-36-
Α.	Description of original monument and accessories and/or subsequent restoration:  Post set in 1815 G.L.O. survey; 24" W. oak S 22°W 28 1ks, 12" W. oak S 79°W 9 1ks.  LCRC, L 7300, P 646  LCRC, L 7947, P 870  LCRC, L 12207, P 881  Stonerock, 1978, ½" rerod  **Ward, 1980, iron rod  **Ward, 1980, iron rod  **N 80°W 55.66' Nail 18" Locust  N 40°E 26.82' Spk 14" Oak  N 20°E 25.79' PK 15" Oak  **S 25°E 40.83' Spk 10" Oak  **S 25°E 40.83' Spk 10" Oak  **S 25°E 40.83' Spk 10" Oak  **S 25°E 40.83' Spk Triple  10" Locust  **N 70°W 55.50' Spk Twin 10" **N 70°W 55.50' Spk Twin Locust  **N 70°W 55.50' Spk Twin 10" **N 70°W 55.50' Spk Twin Locust	
В.	Description of comer evidence found and/or method applied in restoring or reestablishing corner:  Recovered 1/2" rerod at the centerline intersection of Knox and Ellis Roads. Distance south to the SE corner of Section 1 (M-3) checks; 2664.05' mea.; 2664.09' survey by Ward, L 7391, P 118, O.C.R.; 2664.09' record.  Witnesses Found  N 34°E 26.48' PK tag 17623 20" Oak N 89°E 23.97' PK tag 17623 50" Locust *S 26°E 40.77' Nail SW face 16" Oak S 60°W 49.41' PK tag 17623 12" Locust *N 75°W 55.76' PK tag 17623 18" Locust  *Confirms LCRC  *Confirms LCRC	
C.	Description of monument for corner and accessories established to perpetuate locating the position of the corner.  Set 5/8" rerod with 0.C. remonumentation cap, replacing 1/2" rerod  N 60°W 55.33' PK/remon tag S face Twin 12" Locust  N 34°E 26.75' PK/remon tag W face 16" Oak  N 468559.3195	
	S 25°E 40.82' PK/remon tag SW face 14" Oak E 13369598.5505  S 70°W 72.31' PK/remon tag N face Triple 14" Locust  The selected location is accepted by the Contractor and is generally accepted by professi surveyors as the best available evidence of the position of the original corner. This corner was also accepted by the Oakland County Peer Group, as established under Act 345 of P.A. 1990.	Lona

Signed by

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983