SURVEY & REMONUMENTATION

UBER 15235 FC 085

FB 25020801

B. # Chima S. M. S. Action.				\$ 7.00 MISCELLANED	IS RECORDING
MAY - 1 199	LAND CORNI	ER RECORDATION	N CERTIFICATE	\$ 2.00 REMONUMENTA	TION
For corners in	Filing Requir	ement of Act 74, I	Mich. P.A. 1970	2 FEB 95 9:42 A.M.	RECEIPT# 508
Oakland COMMISS	ION		l l		ED - CAKLAND COUNTY
(County)	Located in:	Corner Code =	#	LYNN D. ALLEN, CLER	WEGISTER OF DEEDS
Public Land Survey	T <u>4N</u> R <u>9E</u>	п _0			AA KIMPI I
1. Fublic Land Survey	T R				5MIIH
	T R			Complian	æ with
	T R			ACT 345, P.	
	T R		A	APPROVED ON:	-25-95
_ ·	T R T R			PEER GROUP O	OMMITTEE
Property in Sec. S	T R		Ke	gister of Deeds Stan	ıp & File Number
4. Lot No, Recorded	Plat			ABCDE	= G H J K L N
5. Private Claims				2 6 5 5	
				3	
				4 7 8 9	10-11-12-
I. <u>James J. Scharl</u> , in a fie	ld survey onDe	ecember 19	19 <u>94</u> ,	5	
do hereby certify that under requirement in lines 1 and 2 above were in conform	s of P.A. 74, Michigan P.A. lance with regulations an	of 1970, the corner poil dirules therefore as re	nts mentioned	6 19 17 1	5 15 14 13
current manual of survey instructions of	the United States Depart	ment of the Interior, B	ureau of Land	7	
Management or by a decree of a Court of	Law and/or that the corne	r points mentioned in I	ines 3, 4 and 5	8 19 20 2	22 23 24
above were in conformance with the rule Court of Law; established, re-established	≋ of the Michigan Board (≋hed, monumented, re-r	of Land Surveyors or by nonumented, recover	y a Decree of a ed. found as	9	
expressed below:		,		10 30 29 28	27 26 25
NOTE: Not more than 4 corners, a	ill in the same town ar	nd range, may be re	corded	11	
on this certificate.				12 31 32 3	3435-36
A. Description of original monume	nt and accessories and	t/or subsequent res	toration:	13	
Post set in 1817	LCRC, L5976		LCRC, L663	4 D544	1,100
G.L.O. Survey	N.C. Jones,		Buckerfiel		200
S50°W 28 1ks 18" Elm		od in mon box		bar in mon box	71
NO4°W 61 1ks 12" Elm	N80°W 40.95	PK in curb	•	O' to RR spike	in ID
	N45°E 48.91				tag in DE pole
O.C.R.C. 1958, unk cor	S50°W 84.87		N40°W 66.2	0' to St sign	cag in pn bote
N50°W 42.25' Rd sign S75°E 66.00' 8" Basswood		•		 	
S20°E 67.08' 5" Elm	· •				
S65°W 44.56' 17" Hazelnu B. Description of corner evidence	t, *SW/22 West 2	2658.05', *SE/	22 East 2633	.07'	
Recovered 5/8" rerod in	a monument box 1	located .3 feet	t east of th	e Sashabaw Road	l centerline,
on the centerline of Wal	don Koad.				*****
Witnesses Found				- O	Mich
N 45°E 62.38' PK S face	DE light pole			A Think	see and Cal
N 40°W 69.91' street si N 40°W 139.43' PK S face					HARL
S 45°W 72.85' N & tag N				* * * * * * * * * * * * * * * * * * * *	1 4 1
*West 2657.88' SW corner					SSIONAL & E
*East 2632.65' SE corner				2 . NO	10243
				150000	Control of the contro
+ C	77 D \ 4.		4	LA	ND CONTRACTOR
* Confirms O.C.R.C. (M.S	.H.D.) Witnesses	i		The state of the s	RASHITA
C. Description of monument for co	mer and accessories e	stablished to perpe	tuate locating the	e position of the corr	ner:
Set 5/8" rerod with Oakl					
5/8" rerod.			•		r
N 45°E 62.83' PK/remon	tag S face DE po	le			
S 45°E 79.30' PK/remon	tag N face DE po	1e			
S 40°W 72.80' PK/remon N 45°W 76.97' PK/remon					
	_				
The selected location is	accepted by the	Contractor an	nd is general	lly accepted by	
professional surveyors a corner. This corner was	s the best avail	able evidence	of the posi-	tion of the ori	ginal
under Act 345 of P.A. 19	arso accepte by 90.	cue carrand (Jounty reer	oroup as establ	.18nea
	~ ^				
	11.12.0			20 100 <i>1</i>	
Signed by	-1 - 0 com	D	ateD	ec. 28, 1994	
urveyor's Michigan License No. 🗘	19843		FORM APPROV	VED BY MICHIGAN STATE BDARD Ω	F LAND SURVEYORS, JAN. 28, 1971
	~		, would file 1 1181		REVISED MAY 14, 1975 REVISED JAN., 1983
					MEA-0-0 0-001 1400