		iek RECORDATION CERTII irement of Act 74, Mich. P./	
For corners in	i img nequi	rement of Act 74, mich. Fa	A. 1970
0akland Countyl	Located in:	Corner Code ##	
·	- 427 - 07	T 10	
Public Land Survey	т <u>4N</u> R <u>9E</u> Т R	<u>I-12</u>	Compliance with
	T R		ACT 345, P.A. 1990
	T R		APPROVED ON: 9-27-95 Jom 5
2. Property Controlling in Section	S T R S T R		OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	S T R		
J. Lot No	, Recorded Plat		A B C D E F G H I J K L
. Private Claims			2 5 5 4 3 3 3
			3
			4 7 8 9 10 11 11
	, in a field survey on		
	requirements of P.A. 74, Michigan P. e in conformance with regulations a		the 18-1-17-16-15-14-15-15
	structions of the United States Depa of a Court of Law and/or that the cort		
bove were in conformance	with the rules of the Michigan Board	d of Land Surveyors or by a Decree	eofa
Court of Law; established expressed below:	, re-established, monumented, re	e-monumented, recovered, found	10 30 29 28 27 26 2
	corners, all in the same town	and range, may be recorded	11
on this certificat			12 31 32 33 34 34 35 35
L. Description of origina	al monument and accessories a	nd/or subsequent restoration:	13
•	7 G.L.L. survey	4	
10" W. oak S 28	•		
10 W. oak S 20			\$ 7.00 MISCELLANEOUS RECORDING
			\$ 2.00 REMONUMENTATION
			29 SEP 95 7:30 A.M. RECEIFT# 5B
			PAID RECORDED - DAKLAND COUNTY LYNN D. ALLEN, CLERK/REGISTER OF DEEDS
		•	Pills De Lifferia Arthurineasa ini an arthur
3 Description of corner	r evidence found and/or method	s applied in restoring or reesta	iblishing corner:
s. Description of come	evidence lound and/or method	applied in restoring or receta	
	rerod NW'ly 14.3 ft fr		
	r Ridge Circle in the division recorded in L		2.13
	corner of "Lake Oaklan		
	ecords. Distances mea		m the location & SAMES J. **
			SCHARL SPORTSON
			SURVETOR
			NO. 19843 . NO.
			CANU
Conceintion of manua	ment for comer and accessories	s established to perpetuate lo	caling the position of the corner:
			replacing 1/2" rerod.
			particular in the second secon
	PK/remon tag SE face 1 PK/remon tag E face 18		
	PK/remon tag N face 14		
East 88.23 [†]	PK/remon tag S face 10	" elm	
The selected lo	cation is accepted by	the Contractor and is	generally accepted by professions
			of the original corner. This corner
was also accept	ed by the Uakland Coun	ty reer Group as esta	blished under Act 345 of P.A. 1990
	-		
	20,0	. 0	August 28, 1995
Signed by	ome 1, Jobs	Date	nugust 20, 1333
Surveyor's Michigan Lice	nse No. \ 19843	_	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28,