COPY

LIBER 16874 PC 113

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 7.00 MISCELLANEOUS RECORDING For corners in 2.00 RENOMUMENTATION <u>Oak1and</u> Located In: Orion TwiCorner Code # 3 JAN 97 7:45 A.M. RECEIPT# 78 PAID RECORDED - OAKLAND COUNTY LYNN D. ALLEN, CLERK/REGISTER OF DEEDS 1. Public Land Survey T 4N R 10E H-5 2. Property Controlling Compliance with ACT 345, P.A. 1990 in Section APPROVED ON: 12-17-96 3. Miscellaneous OARLAND COUNTY REMONDATION Property in Sec. PEER GROSS : 124777 Register of Deeds Stamp & File Number 4. Lot No. Recorded Plat 5. Private Claims I Huston K. Kennedy, in a field survey on 11/6, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in 3 conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for United States Department of the Interior, Bureau of Land Management of by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, 5 7 NOTE: Not more than 2 corners, all in the same town and range, may be recorded 9 10 1: A. Description of original monument and accessories and/or subsequent restoration: 1817-GLO Wampler, D.S.; Set Post 24" White Oak N10'E 30 Links; 24" White Oak S01'W 52 Links 1.) 1973-Stonerock, PS #13601; LCRC L.6083, Pg.36 - Fnd Monument Box 2.) 1977-Kennedy, PS \$17623; LCRC L.7037, Pg.885 - Fnd 1/2" Iron Rod in a Monument Box 3.) 1989-Heil, PS #18993; Survey L.11116, Pg.253 - Pnd 1/2" Iron Rod in well SURVEY & REMONUMENTATION MAY 2 2 1997 B. Description of corner evidence found and/or methold applied in restoring or reestablishing corner: COMMISSION 1996 Kennedy Surveying, Inc. - Kennedy, PS #17623 - Fnd 1/2" Iron Rod in a Monument Box 2 feet West of the existing centerline of Pil Tree Road extending to the North, which has a bituminous surface, and in line with the existing centerline of Clarkston Road Witnesses from LCRC #1 & 2, Survey #3 and "CLARRSTON HENINGWAY ACRES" a plat recorded in Liber 64, Page 7 of Oakland County Records were used to recover and verify the location of the found 1/2" Iron Rod in a Monument Box. I accepted the found 1/2" Iron Rod in a Monument Box as the best evidence of the original corner position. goo File Field Measurements see back side of LCRC C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: \2 33 H-5 I replaced the found 1/2" Iron Rod with a 5/8" x 24" Iron Rod w/2" diameter brass cap stamped Oakland County Remonumentation, 1 S85'W 35.45' Set PK & Remon Washer South face Guide Pole SO6 E 64.80' Set PK & Remon Washer East face Power Pole N71 E 105.20' Set PK & Remon Washer SE face Guide Pole N44 E 50.71' Set PK & Remon Washer SE face 13" Locust WHICH OF MICHA MICHIE The selected location is accepted by me and is generally accepted by Professional Surveyors as the perfect of the selected location is accepted by me and is generally accepted by Professional Surveyors as the perfect of the selected location is accepted by me and is generally accepted by Professional Surveyors as the perfect of the selected location is accepted by me and is generally accepted by Professional Surveyors as the perfect of the selected location is accepted by the selected lo 1919 Chigo KENNEDY PROFESSIONA Signed by SURVEYOR 12-18-96 Surveyor's Michigan License No. Date 17623 17623



SURVEY & REMONUMENTATION

MAY 2 2 1997

COMMISSION

PIELD HEASUREMENTS BETWEEN

H-5 to G-5 GLO = 40.955 chains or 2703.03 Ft.
H-5 to I-5 GLO = 40.955 chains or 2703.03 Ft., combined recorded distances from "CLARKSTON HEMINGWAY ACRES" L.64, Pg.7, and "LAKE ORION HEIGHTS NO. 1" L.15, Pg.49 of O.C.R. is 2771.26 Ft., 2773.09 Ft. (MEA 1996)