

MICHIGAN  
DEPARTMENT OF CONSERVATION

~~FORESTRY DIVISION~~

Surveying and Architectural Section

LAND CORNER RECORD

T. 4. NR. 116.

OAKLAND COUNTY

DESCRIPTION OF CORNER N. E. cor. of N.W.  $\frac{1}{4}$  of N.W.  $\frac{1}{4}$  sec 5.

DESCRIPTION OF CORNER MONUMENT 1" iron pipe in fence corner.

WITNESSES TO CORNER Fence running N, S, & W from corner

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner found by running a line west  
from North  $\frac{1}{4}$  corner of section 5

Date of location 12-60.

SURVEYORS SEAL

SIGNED \_\_\_\_\_  
REGISTERED LAND SURVEYOR

DATE 1-24-61