

MICHIGAN  
DEPARTMENT OF CONSERVATION

~~FORESTRY DIVISION~~

Engineering and Architectural Section

LAND CORNER RECORD

T. 1. NR. 11E.

OAKLAND COUNTY

DESCRIPTION OF CORNER Center  $\frac{1}{4}$  Cor. Sec. 6

DESCRIPTION OF CORNER MONUMENT TRACK SPIKE 2" below rd grade

WITNESSES TO CORNER E. of Road Grade;

Spike on line with fence South;

Unable to establish good witnesses.

due to deep road cut

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Established by accepted surveying methods Date Est. 12-61.

SURVEYORS SEAL

SIGNED *H. L. Johnson* DATE 1-24-61  
REGISTERED LAND SURVEYOR