MAY - 1 1995

LAND CORNER RECORDATION CERTIFICATE

93-1010

For corners in

expressed below:

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

OK - 7. 8387	
--------------	--

* 7.VU	пл	うしたしし	.AREUU:	KELL	KLTM	U)	
\$ 2.00	RE	MONUR	ENTAT:	CON			
20 JAN	95	8:14	A.A.	F	RECEI	PT#	12B
PAID		R	CORDE	0 - 0	KLAN	D (C	UNTY
LYNN D	. AL	LEN,	CLERK	/REGIS	TER	OF I	EEDS

Oakland (County)			_ Located In: Oakland Corner Code ##				20 JA	20 JAN 95 8:10 A.M. RECEIPT# 12B									
1.	Public Land Survey		T <u>4N R 11E M-1</u>					PAID RECORDED - OAKLAND COUNTY LYNN D. ALLEN, CLERK/REGISTER OF DEEDS									
			T R							Compliance with ACT 345, P.A. 1990 APPROVED ON:							
2.	Property Controlling	s	т	R			APPRO	OVED	ON:	22	<u>-9-</u>	94	STE A PE	-			
	in Section			R			OAKL					IITTEI		ION			
3.				R			Regist	er of	Deed	s Sta	mp &	File !	Num	ber			
	Property in Sec.	S	Т	R													
	Lot No ,							A B	С	DE	F G	Н	ı J	ĸ	L		
5.	Private Claims							\prod			ŢŢ	Ţ	Ţ	T	Ţ		
							3	1	一 :	ì	i	-3— 			į		
							_				Ţ				Ţ		
ı.C	rant J. Ward, RLS	Sinafi	ald surve	von NOV	ember 3	19 93			T	1	ĭ	—10— 	Γ	T	-		
do	hereby certify that under r	equiremer	its of P.A. 7	74, Michigan P./	A. of 1970, the corner po	intsmentioned		$\mathbf{J} T$							Ţ		
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land						1	<u> </u>	[16	—15— 	14	T	-1				
CU	rrent manual of survey ins inagement or by a decree o	tructions (of the Unite	ed States Depa	artment of the Interior, E perpoints mentioned in	Bureau of Land lines 3, 4 and 5		П	\top		11				1		
ab	ove were in conformance in	with the rul	les of the h	Michigan Board	of Land Surveyors or b	y a Decree of a	ه ٠	19	1-2	0	21-	—22— 	23		-2		

on this certificate.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Court of Law, established, re-established, monumented, re-monumented, recovered, found as

Description of original monument and accessories and/or subsequent restoration:

M-1 Post, per G.L.O. Notes.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - Intersection of Town and Range Line, T. 4 N., R. 11 E. Found P.K. Nail in asphalt, O.2' below as-M-1 phalt in the Centerline/Centerline of Romeo and Dequindre Roads. This corner location is a careful and faithful perpetuation of the position of the original corner. $S_{i}^{m} = I_{i}$

Previously Recorded in L. 6018, P. 06 (2); L. 6634, P. 534 (2); and L. 7082, P. 440 (2) of Oakland County Records.

- Indicates the number of references that confirm this corner by dimensional tie. (n)
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner
 - Intersection of Town and Range Line, T. 4 N., R. 11 E. Set Concrete Monument Box and 5/8" Iron Rod and Brass Cap #22445.

S. 45° W. 46.29

Chiseled "+" in top end of 24" C.M.P.

S. 25° E.

Set P.K. Nail & Brass Disc #22445 in SW. face of Utility Pole. 52.21'

N. 30° E. N. 25° W.

Set P.K. Nail & Brass Disc #22445 in NW. face of Utility Pole. 54.61 Set P.K. Nail & Brass Disc #22445 in NE. face of Utility Pole. 58.62'

S. 62° W. Found G.P.S. Monument #10012. 86.38'

OF MICHIGAN JAIL GRANT J. WARD LAND SURVEYOR NO. GMA 1

Date December 15, 1994

Surveyor's Michigan License No. 22445

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1 REVISED MAY 14, 1 REVISED JAN., 1