

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Holly Twp. OAKLAND COUNTY

T 5N R 7E

DESCRIPTION OF CORNER

SET 1/2" DIA PIPE WITH EXISTING CONDITIONS COMMON TO

CORNER MONUMENT


SEC. 11, 12, 13, 14

DATE MONUMENT PLACED AND WITNESSED

MSHD MARCH 1959

WITNESSES TO CORNER.....

N 45° E 25.81' 10" OAK



S 15° E 31.66' 8" ELM

S 45° W 29.95' FENCE POST

AND

N 65° W 38.46 10" MAPLE

N 20° W 22.04' 20" ELM


CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED


REGISTERED LAND SURVEYOR

DATE

1967

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing