LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

oakland

I. PUBLIC LAND SURVEY. 30 T. 5 N. R. 8 E B-10, C-10 PROPERTY CONTROLL. S. MISCHANDOUS PROPERTY IN SECTION T. N. R. E N. R.	FOR CORNERS OF -:	LOCATED IN-;	CORNER CODE NUMBER	-	
3. MSCRILANEOUS PROPERTY IN SECTION	1. PUBLIC LAND SURVEY30) T. 5 N. R. 8 E.	B-10, C-10		
A. LOT NO	2. PROPERTY CONTROLL- ING IN SECTION——	,T N E. W.			
S. PRIVATE CLAIMS	3. MISCELLANEOUS PROPERTY IN SECTION	,T,NE.			
the corner points mentioned in lines I and 2 above were, in a field curvey on October 9, 19, 25, 19, 24, 19, 24, 19, 25, 25, 25, 25, 25, 25, 25, 25, 25, 25	4. LOT NO , REC	CORDED PLAT			
re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current namual of survey instructions of the United States Department of Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on	5. PRIVATE CLAIMS			1	
B-10 Center Section Found from rod, Albright witnesses (3-22-72) N60°W - 29.25' - 30" Maple S45°E - 28.75' - 36" Cherry (stump) S30°W - 44.25' - 18" Cherry C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: B-10 Center Section Set 1" Pipe over from rod 4" below gravel S34°W - 44.47' - 14" B. Cherry N55°W - 29.33' - 32" Maple N63°E - 49.35' - 12" B. Cherry (clump) N55°W - 29.33' - 32" Maple N63°E - 49.35' - 12" B. Cherry (clump) S56°E - 25.19' - Telephone Pole SIGNED BY SURVEYOR'S MICHICAN REGISTRATION NO. FOR STATE AND UNITED STATES AGENCIES: SIGNED BY APPROVED AND SIGNED BY APPROVED AND SIGNED BY FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1971 FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1971	re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on				
B-10 Center Section Set 1" Pipe over fron rod 4" below gravel S34°W - 44.47' - 14" B. Cherry N55°W - 29.33' - 32" Maple N63°E - 49.35' - 12" B. Cherry (clump) N55°W - 29.33' - 32" Maple N63°E - 43.00' - N. Gate post N29°E - 46.00' - 14" Maple (Clump) S67°E - 25.19' - Telephone Pole SIGNED BY SIGNED BY DATE SURVEYOR'S MICHICAN REGISTRATION NO. SIGNED BY APPROVED AND SIGNED BY MICHIGAN REGISTRATION NO. 18655 LAND FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1871	B-10 Center Section Found iron row witnesses (1 N60 W - 29.25 S45 E - 28.75	n d, Albright 3-22-72) ' - 30" Maple ' - 36" Cherry (stump)	C-10 E & Corner Found iron		
B-10 Center Section Set 1" Pipe over fron rod 4" below gravel S34°W - 44.47' - 14" B. Cherry N55°W - 29.33' - 32" Maple N63°E - 49.35' - 12" B. Cherry (clump) N55°W - 29.33' - 32" Maple N63°E - 43.00' - N. Gate post N29°E - 46.00' - 14" Maple (Clump) S67°E - 25.19' - Telephone Pole SIGNED BY SIGNED BY DATE SURVEYOR'S MICHICAN REGISTRATION NO. SIGNED BY APPROVED AND SIGNED BY MICHIGAN REGISTRATION NO. 18655 LAND FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 26, 1871	C. Description of monument for	or corner and accessories establi	ished to perpetuate locating the	position of the corner:	
4" below grave1 S340W - 44.47' - 14" B. Cherry N550W - 29.33' - 32" Maple N550W - 29.33' - 32" Maple N630E - 43.00' - N. Gate post N290E - 46.00' - 14" Maple (Clump) S670E - 25.19' - Telephone Pole SIGNED BY	B-10 Center Section	n	C-10 E & Corn	er	
S34°W - 44.47' - 14" B. Cherry N55°W - 29.33' - 32" Maple N63°E - 43.00' - N. Gate post N29°E - 46.00' - 14" Maple (Clump) S67°E - 25.19' - Telephone Pole SIGNED BY	•		N63 ⁰ W -	42.03' - 6" B. Cherry	
N55°W - 29.33' - 32" Maple N63°E - 43.00' - N. Gate post N29°E - 46.00' - 14" Maple (Clump) S67°E - 25.19' - Telephone Pole SIGNED BY	\$34°W - 44.47	- 14" B. Cherry			
SURVEYOR'S MICHIGAN REGISTRATION NO. FOR STATE AND UNITED STATES AGENCIES: SIGNED BY APPROVED AND SIGNED BY MICHIGAN REGISTERED LAND SURVEYOR SURVEYOR'S MICHIGAN REGISTRATION NO. 18655 FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971	N55 ^o W - 29.33 N29 ^o E - 46.00	' - 32" Maple ' - 14" Maple (Clump)	N63°E -	43.00' - N. Gate post	
FOR STATE AND UNITED STATES AGENCIES: SIGNED BY DATE DATE DATE APPROVED AND SIGNED BY MICHIGAN REGISTERED LAND SURVEYOR SURVEYOR'S MICHIGAN REGISTRATION NO. 18655 FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1871	SIGNED BY		DATE		
SIGNED BY DATE DATE DATE SUNALUL. APPROVED AND SIGNED BY MICHIGAN REGISTRATION NO. 18655 FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971	SURVEYOR'S MICHIGAN RE	GISTRATION NO		(SEAL)	
APPROVED AND SIGNED BY MICHIGAN REGISTERED LAND SURVEYOR SURVEYOR'S MICHIGAN REGISTRATION NO. 18655 FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1871	FOR STATE AND UNITED S	TATES AGENCIES:		OF MICH	
SURVEYOR'S MICHIGAN REGISTRATION NO. 18655 FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971	SIGNED BY	A	DATE	FO DONALD L. VAN	
FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971	APPROVED AND SIGNED B	MICHIGAN REGISTERED LAN	NO SURVEYOR	ALL-STAY IN THE STATE OF THE ST	
DEVICED MAY 12 10 18	SURVEYOR'S MICHIGAN RE	GISTRATION NO		RD OF REGISTRATION, JAN. 26, 1971	