LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

EORRER OF : LOCATED 18 1. PUBLIC LAND SURVEY 30 T. 5 N. R. 8 E				Oakland	
2. PROPERTY CONTROLL. NG IN SECTION. T. S. R. E. 3. MISCELLASPOIS PROPERTY IN SECTION. T. S. R. E. 4. LOT NO. RECORDED PLAT 5. PRIVATE CLAIMS Donald L. Bissell do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Decober, 1984, and 5 above were, in a field survey on 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey instructions of the United States Department of the Interior, Burson of Land Management of ye decree of a court of law. Furthermore, that the corner points mentioned in lines 1 and 2 above were, in a field survey on 1990, found, recovered, restored, established, and is above were, in a field survey on 1990, found, recovered, restored, established or re-established surpess on the United States Department of the Interior, Burson of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 1, and 3 above were, in a field survey on 1, 1991, found, recovered, restored, established or re-established surpesses of a Court of law. A. Description of original monument and accessories and/or subsequent restoration: B. Description of original monument and accessories and/or subsequent restoration: C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-9 NV Corner Boott apike in mon., box. In G. Orange Hall Road NS 10W - 33, 75 - E. end of N. conc. guard rail S36 2 - 32, 857 - Power pole S39 W - 36, 457 - SE corner of top step bridge abutuent West - 26, 557 - E. end bridge deck SIGNED BY	FOR CORNERS OF -:		CORNER CODE NUMBER		
3. MISCELLANEOUS PROPERTY IN SECTION, RECORDED PLAT	1. PUBLIC LAND SURVEY30	_ T 5 N. R 8 E.	A-9.		
3. MISCELLANEOUS PROPERTY IN SECTION, RECORDED PLAT	2. PROPERTY CONTROLL- ING IN SECTION———	N. E. T S., R W.			
5. PRIVATE CLAIMS		l l			
I. Donald L. Bissell I. Donald I. Bissell I. Donald II. Bissell I. Donald III. Bissell I. Don	4. LOT NO , RECO	ORDED PLAT			
the corner points mentioned in lines 1 and 2 above were, in a field survey on Coccobers, 19, 40, 100 (restablished, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law. A. Description of corner evidence found and/or method applied in restoring or re-establishing corner: A-9 NW Corner Found Boat Spike in mon, box, all old witnesses obliterated by construction of 1-75 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-9 NW Corner Boat spike in mon, box, in § Grange Hall Road M512W = 33,73' = E, end of N. conc. guard rail S36yE = 32,63' = Fower pole S59°W = 36,45' = SE corner of top step bridge abutment West = 28,95' = E, end bridge deck SIGNED BY DATE SURVEYORS MICHIGAN REGISTRATION NO. SURVEYORS MICHIGAN REGISTRATION NO. DATE SURVEYORS MICHIGAN REGISTRATION NO. SURVEYORS MICHIGAN REGISTRATION NO. DATE SURVEYORS MICHIGAN REGISTRATION NO. SURVEYORS MICHIGAN REGISTRA	5. PRIVATE CLAIMS				
A-9 NW Corner Found Boat Spike in mon. box. all old witnesses obliterated by construction of 1-75 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-9 NW Corner Boat spike in mon. box. in g Grange Hall Road N51°W - 33.73' - E. end of N. conc. guard rail S34°E - 32.85' - Power pole S59°W - 36.45' - SE corner of top step bridge abutment West - 28,95' - E. end bridge deck SIGNED BY	the corner points mentioned in lines 1 and 2 above were, in a field survey on October, 1984, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on, 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:				
A-9 NW Corner Found Boat Spike in mon. box. all old witnesses obliterated by construction of 1-75 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-9 NW Corner Boat spike in mon. box. in g Grange Hall Road N51°W - 33.73' - E. end of N. conc. guard rail S34°E - 32.85' - Power pole S59°W - 36.45' - SE corner of top step bridge abutment West - 28.95' - E. end bridge deck SIGNED BY					
A-9 NW Corner Boat spike in mon. box. in g Grange Hall Road N51°W - 33.73° - E. end of N. conc. guard rail S34°E - 32.85° - Power pole S59°W - 36.45° - SE corner of top step bridge abutment West - 28.95° - E. end bridge deck SIGNED BY	A-9 NW Corner Found Boat Spik all old witness	e in mon. box. es obliterated	ied in restoring or re-establishin	g corner:	
SURVEYOR'S MICHIGAN REGISTRATION NO	A-9 NW Corner Boat spike in m in g Grange Ha N51°W - 33.73° S34°E - 32.85° S59°W - 36.45°	on. box. 11 Road - E. end of N. conc. - Power pole - SE corner of top s	guard rail	position of the corner:	
FOR STATE AND UNITED STATES AGENCIES: SIGNED BYCHIE OF BURVE OF MICHIGAN REGISTERED LAND BURVEYOR MICHIGAN REGISTERED LAND BURVEYOR NO. 18655	SIGNED BY		DATE		
APPROVED AND SIGNED BY MICHIGAN REGISTERED LAND SURVEYOR MICHIGAN REGISTERED LAND SURVEYOR NO. 18655	SURVEYOR'S MICHIGAN REG	SISTRATION NO			
APPROVED AND SIGNED BY MICHIGAN REGISTERED LAND SURVEYOR MICHIGAN REGISTERED LAND SURVEYOR NO. 18655	FOR STATE AND UNITED ST	ATES AGENCIES:		TE OF MICHIO	
MICHIGAN REGISTERED LAND SURVEYOR (SENIGVEYOR NO. 18655	SIGNED BY		PATE		
18655	APPROVED AND SIGNED BY	MICHIGAN REGISTERED LA	DATE DATE		
SURVEYOR'S MICHIGAN REGISTRATION NO. 18655	SURVEYOR'S MICHIGAN REC	DISTRATION NO. 186	55		

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975