## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	رب) (رب
1. PUBLIC LAND SURVEY 2	3 T. 5 N. R. 7 E.	K-9	<b>-</b>
2. PROPERTY CONTROLL-9:		K-9	
3. MISCELLANEOUS PROPERTY IN SECTION	,T N. R E. W.		•
4. LOT NO , REC			
			REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1973, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original monument and accessories and/or subsequent restoration:			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  38" I MAR PIN CORNER IS FIELD GREAT LAND. Sub.  Placed Plastic Sap on Iron Fin RLS. # 12029			
3/8" IRON P.N S. 05° E. 19.0 S. 40° E. 10.0 N. 15° E. 26. South 36.0	19' 14" Hickor 19' 4" Oak 69 18" Oak 48 Prop. Cor. S.	RLS. # 12029 (fair) (lof 3 in chare) W. Cor Lot 7 Bik. 1	ting the position of the corner:
All distances +	of the names in tree	-S DATE	
SURVEYOR'S MICHIGAN RE			(SEAL)
FOR STATE AND UNITED S			
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY	MICHIGAN REGISTERED LA	ND SURVEYOR DATE	( SEAL )