

Act 345 of P.A. 1990.

Surveyor's Michigan License No.

THE 19758 R 464

LAND CORNER RECORDATION CERTIFICATE 106278 Filing Requirement of Act 74, Mich. P.A. 1970 1970
LIBER 19758 PAGE 464
\$7.00 MISC RECORDING
\$2.00 REMONMENTATION
03/30/1999 01:03:22 P.M. RECEIPTH 12968
PAID RECORDED - OAKLAND COUNTY
G. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS For corners in Oakland Located In: Corner Code # (County) 1. Public Land Survey STIRVEY & Compliance with TATION ACT 345, P.A. 1990 6-15-58 55 2. Property Controlling in Section OAKLAND COUNTY REMONUMENTATION 3. Miscellaneous PEER GROUP COMMITTEE Property in Sec. SECTION Register of Deeds Stamp & File Number _, Recorded Plat 5. Private Claims I, <u>Timothy J. Hart</u>, in a field survey on <u>3-30</u>, 19 <u>98</u> do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. 11 A. Description of original monument and accessories and/or subsequent restoration: Post set on Township line East 24 1ks of Atlas Township corner in 1823 G.L.O. survey; 10" W. Oak S 181°W 93 1ks; 11" W. Oak S 31°E 70 1ks. J HART A) LCRC, L6373, P850, Albright, 1971, fd "T" iron (2) ROFESSION B) Survey, L6845, P592-593, Kieft, 1977, fd "T" bar (1) C) Survey, L16901, P175-176, Lillieberg, 1996, fd "T" bar (6) SURVEYOR (n) indicates number of witnesses confirmed B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Recovered tee bar 5 ft east of the centerline of Thayer Road on the centerline of County Line Road, running east. Another tee bar was recovered 9.61 ft west for the Atlas Township corner. Easterly tee bar accepted as corner as supported by G.L.O. notes and acceptance by Albright, Kieft and Lillieberg. The westerly tee bar was accepted as corner G-13 of Atlas Township even though Flint Surveying referenced this corner as the Groveland Township corner on numerous surveys. (L) indicates LCRC or survey confirmed Witnesses Recovered S 35°E 49.11' Nail/tag N. 20" Hickory (A&C) East 2696.12' to H-1 (B&C) S 40°E 46.80' PK nail E. 8" Elm N 55°W 45.50' PK/tag W. face 10" Ash N 40°W 90.75' Nail/tag N. DE pole (C) N 35°E 43.43' Nail/tag W. 10" Elm (C) West 60.41' PK nail S. DE pole (A&C) 9.61' Tee bar corner G-13, Atlas Twp (C) West C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" rerod w/O.C. Remon brass cap, replacing tee bar. N 40°W 90.95' PK/remon tag NE util pole State Plane Coordinates 43.40' PK/remon tag W. 10" Elm 49.00' PK/remon tag N. 20" Hickory N 35°E N 502209.9189 S 35°E E 13352287.7808 S 60°W 66.40' PK/remon tag N. util pole The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. This corner was also accepted by the Oakland County Peer Group as established under

Date