

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	corners in	· .	riequaen	TIORE OF MOETING HINDER L	.m. 1010	106309	
	Oakland (County)	Located In:		Corner Code #	I LIBE	R 19758 PAGE 495	
	,			t	\$7.0	O MISC RECORDING	
	Dublin Land Comes	T 5N	R 8E	1-12	92.0	00 REMONUMENTATION 30/1999 01:03:22 P.M.	RECEIPT# 12968
1.	Public Land Survey		R	T-12	PATI) RFCORDED - OAKLAN	D COUNTY
			R		G. V	IILLIAM CADDELL, CLERK Compliance with	/KEGISIEK OF DEE
		· + —	. n	SURVEY &		ACT 345, P.A. 19	990
2	Property Controlling	s †	RBE	J. JATION	4 000	OVED ON: 1.27	·99 JS
۷.	in Section	S T		5 - 5-1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1		AND COUNTY REMON	UMENTATION
3.	Miscellaneous	s T		MAR 2 1 2000		PEER GROUP COMM	HTTEE
	Property in Section	s T		MV H +	Regis	ster of Deeds Stamp	& File Number
	, ,			and the second to delive the bit			
4.	Lot No.	, Recorded Plat	····	SECTION		ABCDEF	g н I Ј К
5.	Private Claims	····					
						2 5 1 5	1-3-1-2-1-
						3	
				# 00		4-7-1-9-1-9-	10-11-
l, _	Timothy J. Hari	, in a field survey on	fishioso D A	5-23 , 19 98	S	5	
				of 1970, the corner points men es therefore as required in the		6 - 18 17 16 -	15 14
mai	nual of survey instruction	ons of the United State	s Departme	nt of the Interior, Bureau o	f Land	7	++++
				ner points mentioned in lines 3		8 19 20 21 -	2223
				rd of Professional Surveyors old, re-monumented, recovered		9	
	expressed below:	oldonoriou, ib coldonoriou	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		,	10 30 29 28	27 26
NO	TE: Not more than 4	comers, all in the same	town and r	ange, may be recorded	,	11	
	on this certificate		101111111111111111111111111111111111111	anigo,ay ao 12001222		12 31 32 33	34 - 35
				44		13	
A.				d/or subsequent restoratio . Oak N 39°E 32 1ks		. Oak S 25°W 82	lks.
			,				
	LCRC, L6194, P.			LCRC, L6212, P260),		
	Jones, 1973, fo	' 20" Box elder		Stonerock, 1973 *N 30°E 62.42'	12" Locus	2 f *	
	*S 36°E 32.70			*S 50°E 32.67'			
	*S 44°W 67.60			0 50 11 5110,			
		F *					10
			ký.				15
			7'				l
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:							r
	Recovered 1/2" rerod at the centerline intersection of Oakhill Road						
	running south and east and Jossman Road running north.						
	Witnesses Recovered STATE OF MCC.						XXXVIII.
	*N 20°E 63.41	Nail/tag NW 24	" Locus	t		JO THOM	Serve.
		' Nail/tag S. 16				J. J. HART	**
	*S 45°E 33.20' Nail/tag N. 6" Box elder					2 * PROFESSIO	• 4 5
		' Nail/tag NE DE				A C SURVEYO	R 4E
		' Nail/tag SE DI ' Nail/tag NW DI				3 8: No 2212	
	5 45 W 67.91	, Nati/Lag NW Di	2 bore			7	S.E
•	*Confirms LCRC	,				THE LAND	S.C.
	"COMPTIME DONG	•	`			A CHILLIAN	lies.
C.	Description of monu	ment for corner and a	ccessories	established to perpetuate	locating the	position of the come	r:
	•			ion brass cap, rep	_		
	•						
	N 45°W 83.60'	PK/remon tag E.	34" Sp			e Coordinates	
		PK/remon tag W.			473413.41 13358694		
	N 45°E 53.65' PK/remon tag S. 16" Locust E 13358694.1133						
S 45°E 33.20' PK/remon tag NE 4" Box elder S 45°W 67.86' PK/remon tag N. DE pole The selected location is accepted by the Contractor and is generally acce							
						rally accepted 1	by profes-
	sional surveyors as the best available evidence of the position of the original corner.						
	This corner was also accepted by the Oakland County Peer Group as established under						
	Act 345 of P.A		•	•	•		
		Λ	- ~ /				
Sin	ned by Fin	with Or	Vien	Date	1-1	23-99	
•	rveyor's Michigan Lice	anse No	33136			IIGAN STATE BOARD OF PROFESSION.	AL SURVEYORS, JAN. 28, 197
oul	veyor a witchigan Lice	עטווי ספוויכ	<u> </u>	1 41111			REVISED MAY 14, 19

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197 REVISED JAN., 197