

T5N, R9E

Monument No. 3-

## Monument Record.

o. 1. Corner to sections 5-6-7-8.

In place of stone.

Standard monument.

s. In line of trees along line between sections 5+6 and 7+8.

4" black oak. S 80° E 7.8 feet.

3" poplar N 1° W 0.9 "

Station in center of road is 98.88 feet southward along section line. an iron pipe and an iron pipe on north side of road is 64.42 ft distant on same line.

Page 42 field notes for recovery-

e + e' On road traverse. a 1" iron pipe in center line road on section line between 7+8 98.88' South of section corner.

A 1" iron pipe is 34.46' northward of this point on north side of road. e is 22.3 ft from fence-

o. 2. N. Side road. at "d" of road traverse. 33.05 from center of road where there is an iron pipe.

4" poplar N 30° W 3.6 feet

4" " S 80° E 8.2 "

d - An iron pipe in road opposite Monument distant 33.05 therefrom. 71

No 3

On s side road thru park at point C of road traverse. 35.99 feet south along 1/8 line from C in center of road

16" B.O. S 66° E 38.0 feet

6 B.O. N 5° W 29.9 feet.

Standard monument.

C

In center line road at angle in park boundary, on 1/8 line in section 6. 35.99' south to monument No 3.

No. 4

On Section line between sections 6+7, (PGA) 664.34' from section corner to east. + 1/8 post west

10" B.O. N 29° W 6.2 feet

12" B.O. N 25° E 4.9 feet

Standard monument.

Nos -

At angle in road traverse park on N side opposite b of traverse and distant 33.08 therefrom.

No permanent trees used

"b"

Opposite Monument No. 5. 33.05 distant in N track road