Jul 1995 1 2 8 5 9 4

LAND CORNER RECORDATION CERTIFICATE

C	0	P	Y
---	---	---	---

For corners in	Filing Requirement of Act 74, Mich. I	P.A. 1970 17.00 HISCELLANEOUS RECORDING
Oakland	Located In: Oxford Twp. Corner Code #	\$ 2.00 KENUNUNEN INT TUN
(County)		19 JUL 95 9:33 A.N. RECEIPT# 8A
		PAID RECORDED - OAKLAND COUNTY
Public Land Survey	T 5 N R 10 E G-8	LYNN D. ALLEN, CLERK/REGISTER OF DEED
	T R	1
	T R	Compliance with
	T R	ACT 345, P.A. 1990
Property Controlling	ST R	APPROVED ON: 7-12-95 7om5.
in Section	ST R	OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE
Miscellaneous Property in Section	ST R ST R	Register of Deeds Stamp & File Number
, Joherth III Gection	3	riogister of Deeds Stamp & File (40/1164)
I. Lot No,	Recorded Plat	
. Private Claims		A B C D E F G H I J K
		2 6 - 5 - 4 - 5 - 2 - 1 - 2
*		3 + + + + + + + + + + + + + + + + + + +
		4-7-4-4-4-41-4-11-4-11-4-11-4-11-4-11-4
Huston K. Kenne	dyin a field survey on June 14, 19 95	, 5
Ineredy certify that under realines 1 and 2 above were in	equirements of P.A. 74, Michigan P.A. of 1970, the comer points ma conformance with regulations and rules therefore as required in the	entioned 6 18 17 18 15 14
anual of survey instructio	ns of the United States Department of the Interior, Bureau of	of Land 7
fanagement or by a decree	of a Court of Law and/or that the comer points mentioned in lines \$	3. 4 and 8 19 20 21 22 23 23
above were in conformance	e with the rules of the Michigan Board of Professional Surveyors tablished, re-established, monumented, re-monumented, recovered	or by a
expressed below:	tabilistieu, 19-establistieu, mortumenteu, re-monumenteu, recovered	10 30 29 28 27 26 3
OTE: Not more than 4 c	omers, all in the same town and range, may be recorded	11
on this certificate.		12 31 32 33 34 34 35 35
	i monument and accessories and/or subsequent restoration	13
		V .
	٠.	
		4
. Description of corner	evidence found and/or method applied in restoring or rees	stablishing comer
		· -
G-9. When the surv	Inc Kennedy, PS #17623 - I recovered the corner (G-8 ey crew was setting the concrete monument at the corner the East to H-24 Highway in the early 1950's, however, Dunla	ev dug through an old road bod. Dumlan Poad did oyt
PIEID WASTER TO	BANKE	
G-7 to G-9 6292.60	Ft., GLO = 80 chains or 5280.00 Ft.	
G-7 to G-8 3146.30	Ft., GLO = 40 chains or 2640.00 Ft.	_
G-8 to G-9 3146.30	Pt., GLO = 40 chains or 2640.00 Ft.	مار _ي م
		32
		*•
	ent for corner and accessories established to perpetuate	
G-8 I set a 1/2" Iron Re PS #17623	od encased in a 4" concrete cylinder 36" long w/2" diamet	er brass cap stamped Oakland County Remonumentati
W81 W 105.56' Set P	K & Remon. Washer South face 7" Poplar	
N74 W 71.39' Set PK	& Remon. Washer SW face 10" Poplar	
W22 W 39.76' Set PK	& Remon. Washer NB face 6" Poplar	
#27 ₹ 1/8.89, Set b	K & Remon. Washer NW face 8" Poplar	MARINIAN CONTRACTOR OF THE PROPERTY OF THE PRO
The selected location i	s accepted by me and is generally accepted by Profession	nal Surveyors as the hest and TE OF MICLE
position of the origina	l corner.	mer periods as one nest destructs entires (1)

17623

Surveyor's Michigan License No.