

118FP 15517FC 421

LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Requirement	of Act 74, Mich. P.A.	1970 \$ 7.00 MISCELLANEOUS RECORDING
Oakland (County)	Located In:Oxford Twp.	Corner Code #	\$ 2.00 REMONUMENTATION 14 JUL 95 8:39 A.M. RECEIPT# 98 PAID RECORDED - DAKLAND COUNTY
1. Public Land Survey	T <u>5 N</u> R <u>10 E</u> T R T R	M-8	LYNN D. ALLEN, CLERK/REGISTER OF DEEDS
in Section S	T R S T R S T R		Compliance with ACT 345, P.A. 1990 APPROVED ON: 6-21-95 Ton 5 OAKLAND COUNTY REMONUMENTATION PERFORMANCE OF THE COUNTY REMONUMENTATION
	S T R S T R		PEER GROUP COMMITTEE Register of Deeds Stamp & File Number
4. Lot No, Record 5. Private Claims, Huston K. Kennedy, in a do hereby certify that under requirent in lines 1 and 2 above were in conformanal of survey instructions of Management or by a decree of a Co 5 above were in conformance with Decree of a Court of Law; established as expressed below: NOTE: Not more than 4 corners on this certificate.	field survey on April 2 ments of P.A. 74, Michigan P.A. of 19 mance with regulations and rules the the United States Department of ourt of Law and/or that the corner po the rules of the Michigan Board of ed, re-established, monumented, re- es, all in the same town and range	70, the comer points mention refore as required in the curr the Interior, Bureau of La ints mentioned in lines 3, 4 a Professional Surveyors or b monumented, recovered, fou	rent 7 13 14 13 15 14 13 15 14 13 15 14 13 15 14 13 15 14 13 15 14 13 15 14 15 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15
A. Description of original mon- 1818-GLO Wampler, D.S.; Set 1		subsequent restoration:	

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - 1995 Kennedy Surveying, Inc. Kennedy, PS #17623 Fnd 3/8" Iron Rod at the surface in the woods with an old fence row extending 1 the North, South & West. This corner is also being used and accepted as a common corner with the West 1/4 corner of Section 19 T5N, R11E, Addison Twp. (A-8)

Witnesses from Unrecorded Survey #1 & 2 were used to recover and verify the location of the found 3/8" Iron Rod.

I accepted the found 3/8" Iron Rod as the best evidence of the original corner position.

FIELD HEASUREMENTS BETWEEN

H-8 to H-7 2605.22 Ft., GLO = 40 chains or 2640.00 Ft. M-8 to M-9 2851.48 Ft., GLO = 40 chains or 2640.00 Ft.

1.) 1977-Kennedy, PS #17623; Unrecorded Survey - Fnd 3/8" Iron Rod 2.) 1990-Kennedy, PS #17623; Unrecorded Survey - Fnd 3/8" Iron Rod

- . Description of monument for corner and accessories established to perpetuate locating the position of the corner.
 - H-8 I replaced the found 3/8" Iron Rod with a 1/2" Iron Rod encased in a 4" diameter concrete cylinder 36" long w/2" diameter bras cap stamped Oakland County Remonumentation, PS #17623

NO3'W 9.17' Set PK & Remon. Washer West face 24" Oak

H83'W 21.70' Set PK & Remon. Washer HE face 10" Oak S39'W 29.17' Set PK & Remon. Washer SE face 10" Oak

S65 R 41.10' Set PK & Remon. Washer SW face 23" Oak

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best position of the original corner.

Date

apanana manana OF MICHIA HUSTON KENNEDY OFESSIONA

7623