MAY - 1 1995

LAND CORNER RECORD

Filing Requirement of Act 74, Mich. P.A. 1970

or	corners	
	Oakland	1

COMMISSION

OK _ T CAMPL

, ,	Oakland	Sitt between	3 45-0 9 11				
_	(County)		Located In:		Corner Code ##	\$ 7.00 MISCELLANEOUS RECORDING	
1.	Public Land Survey					\$ 2.00 REMONUMENTATION 15 JUL 94 7:31 A.M. RECEIPT# 1A PAID RECORDED - DAKLAND COUNTY	
			T	R		LYNN D. ALLENnyGLEGEKAREGISTER OF DEEDS ACT 345, P.A. 1990	
2.	Property Controlling	s	T	R		APPROVED ON: 12-15-93	
	in Section	s	T	R		OAKLAND COUNTY REMONUMENTATION	
3.	Miscellaneous	s	T	R		PEER GROUP COMMITTEE Number	
	Property in Sec.	s	т	R			
4.	Lot No	, Recorde	d Plat	······································		— A B C D E F G H I J K L	
5.	Private Claims						
						3 1 1 1 1 1 1 1	
						° 	

November 9 **Bruce Antcliff** in a field survey on 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in tines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

G-1 GLO **County Witness**

SE - 53.25' Nail 12" Oak

L.C.R.C. L. 5849, P. 478 (1972) 1/2" Iron Bar

93

Post

Iron Pipe West - 21.8' Nail 24"

NE - 52.84' N/W, 10" Oak

West 21.48' N/W, 48" Oak

SE - 28.71' N/W, 14" Oak

East - 32.97' Iron Bar

L.C.R.C. L. 6279, P. 705 (1974) 1/2" Iron Rod

N 25° E - 52.85' 10" Oak S 70° E - 28.74′ 14" Oak West 21.52' 38" Oak

Survey L. 6279, P. 794 (1974) 1/2" Iron Same as L.C.R.C. L. 6279, P. 705

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2"rebar ± 7" West of west edge of gravel road (Haven Road). Checks the following witnesses:

> **County Witness** West 21.8 24" Oak

L.C.R.C. L. 5849, P. 478

Nail and Tag in 48" Oak - West - 21.48'

Nail and Tag in 14" Oak - SE - 28.71'

L.C.R.C. L. 6279, P. 705 S 70° E - 28.74' 14" Oak West - 21.52' 38" Oak

MICHIG

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Set 5/8" rebar with standard Oakland County cap.

P.K. Nail and Brass Tag in N Face 48" Oak - N 80° W - 21.97"

P.K. Nail and Brass Tag in E Face 14" Oak - N 35° E - 52.90'

P.K. Nail and Brass Tag in S Face 14" Oak - S 65° E - 28.32'

P.K. Nail and Brass Tag in SW Face 12" Oak - S 10° E - 75.10'

BRUCE ANTCLIFF SURVEYOR 25826 IAND UMONING COM

25826

Date 1-11-94

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983