

MAY - 1 1995

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

OK - T. SMITH

For corners in  
Oakland

COMMISSION

\$ 7.00 MISCELLANEOUS RECORDING  
\$ 2.00 REMONUMENTATION  
15 JUL 94 7:27 A.M. RECEIPT# 1A  
PAID RECORDED - OAKLAND COUNTY  
LYNN D. ALLEN, CLERK/REGISTER OF DEEDS  
Compliance with  
ACT 345, P.A. 1990

APPROVED ON: 2-2-94  
OAKLAND COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE  
Register of Deeds Stamp & File Number

	Located In:		Corner Code #
	5N	11E	
1. Public Land Survey	T _____	R _____	1-5
	T _____	R _____	
	T _____	R _____	
	T _____	R _____	
2. Property Controlling in Section	S _____	T _____	
	S _____	T _____	
3. Miscellaneous Property in Sec.	S _____	T _____	
	S _____	T _____	

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Bruce Antcliff, in a field survey on November 12, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1-5 GLO Post  
L.C.R.C. L. 7037, P. 843 (1977)  
1" Iron Pipe  
S 22° E - 81.54' Oak  
S 30° W - 55.75' P. Pole  
N 45° E - 52.76' P. Pole

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1-5 Found 1/2" rebar ± 4' West of centerline Rochester Road.  
Checks the following witnesses:  
N 45° E - 52.76' Power Pole

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1-5 The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.  
Set 5/8" rebar with standard Oakland County cap in existing monument box.  
P.K. Nail and Brass Tag in S Face Double 12" Maple - West - 40.63'  
P.K. Nail and Brass Tag in NW Face P. Pole - N 50° E - 52.87'  
P.K. Nail and Brass Tag in NE Face P. Pole - S 26° E - 63.91'  
P.K. Nail and Brass Tag in SE Face P. Pole - S 25° W - 75.87'

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

*File*

Signed by Bruce Antcliff Date 7-11-94  
Surveyor's Michigan License No. 25826

