SURVEY & REMONUMENTATION

UBER 14833 PG 125

94 193369

MAY - 1 1995

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

OK - T. SMITH

Fo	or corners in Oakland	S SI Y KAMBO DENG I COMPANIA IA IN	•		<u></u>	5	ione.	ڻ گ	W		Ê		
	COMI	VIISSION Located In:	Corner Code ##	.	7.00	MYSCI	EI I A	NEGUS	DEM	nont	M.C		
	(County)	5N 11E	L-1	_				negos Ntati		WDI	NO		
1.	Public Land Survey	T R T R		_ 15 _ PA	S JUL 9 AID	4 7	:29 Rec	A.M. ORDED	- O	AKLA		COUN	TY
		T R T R		1	MN D.						. UF	DEE.	UD
2.	Property Controlling in Section			- API	ACT 345, P.A. 1990 APPROVED ON: 3-3-94 OAKLAND COUNTY REMONUMENTATION								
3.	Miscellaneous	S T R		Regi	ister o	ER G	ROL	IP CO	MMF	TE	ă	her	•
	Property in Sec.	S T R				_							
4.	Lot No.	, Recorded Plat			A : 1	3 C	D	E F	G	H i	ı j	ĸ	L N
5.						_ <u>_ </u>	Ť	ŤΪ	Ť	Η̈́	Ť	Ť	"
					2	+	- 5— 	 	+	3-1	— ż	+	-1-
	Bruce Antcliff	N	ovember 8	93	3 4		†						- -
İ, "		, in a field survey on		_	5	\bot	Ľ.	LĽ		لــــّا	LÏ.		Ĺ.
ф	hereby certify that under	requirements of P.A. 74, Michigan P.	A. of 1970, the corner points	mentioned	6		17_		工	[]		<u> </u>	_
		e in conformance with regulations structions of the United States Dep	•		7		Ï	ΙΪ		Ľ	LÏ		Ĭ
	•	of a Court of Law and/or that the cor			8	T							
		with the rules of the Michigan Board			9		-20-		T '	"	-23	Т	-24
	•	d, re-established, monumented, re	e-monumented, recovered,	found as	10		Ţ		\top			T	
	pressed below:				11 -3	`	-29 	 28 	1-	7-1	—26 	+	-25
NC	OTE: Not more than 4 on this certifica	4 corners, all in the same town ite.	and range, may be recor	rdeđ	12		32			<u> </u>	1		1
					13	`]	Ĺ	LΪ	`	لــــّـ	ЩĬ		Ľ
A.	Description of origin	al monument and accessories a	ind/or subsequent restor	ation:			•						
	L-1 GLO	County Witnesses		L.C.R.C.	L. 6663	. P. (651	(1976	i)				
	Doot	NIM OF ELLISCIS DE	A	1/2" Pino		-		•	-				

Same as L.C.R.C. L. 6663, P. 651

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SE - 158.5' - Nail in 20" Pear

SSE - 56.7' - Nail in 12" Cherry

L-1 Found 1/2" Pipe at center line intersection of Secord Lake and Bordman Road. Checks the following witnesses:

> L.C.R.C. L.6663, P. 651 (1976) PK Nall in 6" Ash - NW - 70.31' PK Nail in Tel. Pole - NE - 62.91'

Survey L. 6663 P. 646 (1976) Same as L.C.R.C. L. 6663, P. 651

PK Nail in 6" Ash - NW - 70.31' PK Nail in Tel. Pole - NE - 62.91'

Survey L. 6663 P. 646 (1976)

PK Nail in Anchor Post - SE - 36.38'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.
 L-1 The selected location of a corner, although not established by the original government survey,

is accepted as the best available evidence of the position of the corner.

Set 5/8" rebar with standard Oakland County cap.

P.K. Nail and Brass Tag in W face P. Pole - N 40° E - 63.00' P.K. Nail and Brass Tag in E face 12" Ash - N 10° W - 70.45' P.K. Nail and Brass Tag in W face Tw. 12" Ash - S 20° E - 51.36' P.K. Nail and Brass Tag in SW face 20" Ash - N 85° E - 109.09'

2500 TOTAL SEE.

BRUCE
ANTGLIFF
SURVEYOR
No.
25826

Signed by Bruce Contact 25826
Surveyor's Michigan License No.

Pate 1-11-94

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28. 1971 REVISED MAY 14. 1975

REVISED MAY 14, 1975 REVISED JAN., 1983