





LAND CORNER RECORDATION CERTIFICATE 7.00 HISCELLANEOUS RECORDING MAY - 1 1995 Filing Requirement of Act 74, Mich. P.A. 1970 \$ 2.00 REMONUMENTATION COMMISSION For comers in 2 FEB 95 7:26 A.M. RECEIPT# 2B RECORDED - CAKLAND COUNTY Located in: Addison Corner Code # PAID Oakland (County) Township LYNN D. ALLEN, CLERK/REGISTER OF DEEDS OK - T. SMITH **Public Land Survey** 5N R 11E Compliance with ACT 345, P.A. 1990 12-12-94 APPROVED ON:. OAKLAND COUNTY REMONUMENTATION R **Property Controlling** PEER GROUP COMMITTEE in Section Register of Deeds Stamp & File Number Miscellaneous T R Property in Sec. , Recorded Plat Private Claims in a field survey on July 20 .94 Randy Kolehouse do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a established, re-established, monumented, re-monumented, recovered, found as Court of Law; expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: A. Per G.L.O. notes, J. Wampier set a post in 1817. M-7 J. Smith Survey 1990 Recorded Survey L. 6609 P. 160 1975 L.C.R.C. L. 9248 P. 636 1985 5/8" Iron Rod 38.48' SE to Form Nail in Disc. #123 N Face Utl. Pole 1/2" Iron Rod S 45° W 36.88' P.K. N Side 34" Oak P.K. in 6" Twin Oak NW 92.64' 36.73' SW to P.K. NW Face 30" Oak P.K. in 36" Oak SW 36.85" S 60° E 34.66' P.K. S Side 33" Oak 45.68' NW to Form Nail in Disc. #123 in SW Face of 42" Oak N 80° E 35.86' P.K. NE Side 17" Oak P.K. in 30" Oak SE 34.66 P.K. in 16" Oak ENE 35.83' Description of corner evidence found and/or method applied in restoring or reestablishing corner: В. Found 1/2" iron rod in C/L of Dequindre Road (gravel) running N-S and at C/L of Frick Road West (gravel) running West with a N-S fence 44' East and checked the following witnesses. L.C.R.C. L. 9248 P. 636 1985 S 45° W 36.88' P.K. N Side 34" Oak S 60° E 34.66' P.K. S Side 33" Oak N 80° E 35.86' P.K. NE Side 17" Oak J. Smith Measures 2661.60' to M-8 Description of monument for corner and accessories established to perpetuate locating the position of the corner: C. Set a 5/8" rebar with brass cap stamped "Oakland County Remonumentation P.S. #25854" in place of found 1/2" iron rod. PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in E. Side of E'ly Twin 8" Oak N 10° W 92.64' STATE OF MICH PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in N Side 34" Oak S 45" W 36.88' PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in S Side 33" Oak S 60° E 34.66' RANDY J. PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in NE Side 17" Oak N 80° E 35.86'

The selected location is accepted by the Contractor and is generally accepted by professional

surveyors as the best available evidence of the position of the original corner.

Signed by_

Surveyor's Michigan Licensé No

SO LAND SUR PROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

KOLEHOUSE LAND

25854

REVISED JAN., 1983