REMONUMENTATION

APR 2 4 1995

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN COUNTY OF OCCASA ECELYPO POLLEGOER

100568

COMMISSION For corners in

OCEANA

Filing Requirement of Act 74, Mich. P.A. 1970

JAN -4 P3:23

	Located In:	Corner Code ##	A programme and
(County)			Jung E. Traction
 Public Land Survey 	т <u>13N</u> в <u>17</u> W	<u>C-9</u>	F KEERSTER OF DECUS
	T R		•
	T R		
	T R		
2. Property Controlling	S T R		
in Section	S		
3. Miscellaneous	S R		Register of Deeds Stamp & File Number
Property in Sec.	S T R	<u> </u>	Trogicio di Bocas Biamp a i ne Maniber
•		•	
4. Lot No, Re	ecorded Plat		
5. Private Claims			
			2 - 6 - 5 - 4 - 4 - 3 - 4 - 2 - 1 - 1
			3
			4 7 - 1 8 9 - 10 - 11 - 12 -
J. Randolph Hepwort	The a field survey on Novembe	er 11, 19 ⁹³	. 5
	uirements of P.A. 74, Michigan P.A. of	•	01 10 1 17 10 16 14 13
	conformance with regulations and	•	_1
	ctions of the United States Departm Court of Law and/or that the corner p	•	
,	the rules of the Michigan Board of	•	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
	e-established, monumented, re-mo	• •	
expressed below:			10 30 29 28 27 26 25

Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

C-9 CORNER COMMON TO SEC 19, 20, 29, 30 GRANT TWP T13N, R17W

14" HEMLOCK N30°W 29.0

GLO SET POST 12" BEECH N36°E 29.0 14" HEML BOOK B-12, FF WETMORE, 1900; OLD CORNER- NO DESCRIPTION OR WITNESSES

BOOK B-38, FF WETMORE, 1901; OLD CORNER IRON BOLT ETC- NO WITNESSES BOOK C-10, FF WETMORE, 1900; OLD CORNER-NO DESCRIPTION OR WITNESSES BOOK C-24, FF WETMORE, 1901; OLD CORNER IRON BOLT ETC-NO WITNESSES

BOOK C-60, WM EATON, 1904; OLD CORNER, IRON BOLT ETC- NO WITNESSES

OCRC, SAME AS MOSH

on this certificate.

MDSH, 1969; FD 2" AXLE SHAFT BURIED 12" POWER POLE \$35°E 55.77

FNC POST N40°W 45.11

NW COR 1-S-F-HOUSE S50°W 102.36

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner

I found in the surface at the center of an north-south asphalt road and at the center of an east-west gravel road a 1/2" Iron. Distance measurements north, south and east are close to MDSH distances shown on US31 HWY plans. Upon excavation, I found the 1/2" Iron to be a riser for an axle shaft with a 2" top and with a 6" gear and with a 1" round center shaft about 18" below surface.

No MDSH witnesses are still standing. This corner is substantially as described by MDSH. The 1/2" Iron riser above the axle shaft IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

C-9 CORNER COMMON TO SEC 19, 20, 29, 30 GRANT TWP T13N, R17W

SET "COUNTY SURVEYOR" HARRISON 4"X20" CAST IRON MONUMENT above the found axle shaft

C/L N-S PAVEMENT; C/L E-W GRAVEL ROAD

PK NAIL E FACE 60d SPK E FACE POWER POLE S34°E 58.96 **EDM** 18" MAPLE S07°W 212.64 **EDM** PK NAIL N FACE POWER POLE/TRANSF S79°W 200.40 EDM PK NAIL W FACE **POWER POLE** N07°F 260.98 **EDM**

> Oceana County Remonumentation Peer Group Reviewed & Approved

18-93

J. Kandolph Hepworth Oceana County Surveyor

November 8,

MINISTED LAN 1994

Signed by

Surveyor's Michigan License No.

26457

avoit th

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

Milling

RANDOLPH

HEPSYORTH

LAND SURVEYOR

30.

TO LAND

REVISED MAY 14, 1975 REVISED JAN., 1983