

MAY 1 6 1997

STATE OF MICHIES! COUNTY OF OCEAN RECEIVED FOR PER

DEC 19 ATT 117

LAND CORNER RECORDATION CERTIFICATE COMMENT

Filing Requirement of Act 74, Mich. P.A. 1970

Oceana	Located In:	Corner Code #									
(County)	Locateu III.	Corner Code #	1		Qu		¢.	. ,.	·2	****	مسلم
Public Land Survey	T 13N R T R T R T R		 	,¢		REO	ع ISTER	OF DE	LEOS	e rei	*نعد*
Property Controlling in Section	ST R ST R		-								
3. Miscellaneous	S T R		-								
Property in Section	S T A		Regi	ster of	Deed	ds Sta	amp 8	k File	. Nu	mbe	r
4. Lot No	, Recorded Plat										
5. Private Claims				^-	Ĭ	T		G H	- 	1	Ĺ
				5 6		~5		 	\top	- ģ —	
				3						1	
I.T Danfolm Heremeth	in a field europy on	7mm 1 1 10	00			- -	-1-	10	\top	11	-1
do hereby certify that under	requirements of P.A. 74, Mich	April 1 . 19 migan P.A. of 1970, the corner points	<u> প্রচ</u> , a mentioned	٦							
In lines 1 and 2 above were li	n conformance with regulation	ns and rules therefore as required in	the current	6 18	-	77	16	15.		14	
		Department of the Interior, Burea at the comer points mentioned in lin							\top	1	1
,		nigan Board of Professional Survey	,	8 19	,	20	21	55.		23	
•		onumented, re-monumented, recovi	. ,	10-30	-	29	28	27	_	26-	2
NOTE: Not more than 4 on this certificate		wn and range, may be recorded	I	11 12 31	-	32-	-33	34	1	35	3
A Description of origin	al monument and access	ories and/or subsequent restor	ration	13				<u> </u>			
A Description of ongin	a monument and access	ories andror subsequent restor	audii								

L-7 1/4 Corner Common to Sections 13 & 24 T13N, R17W **Grant Township**

GLO SET POST 12" Cedar for Post No witnesses given!

Book C, Page 78; H.C. Salisbury, 1908; "Corner set by Wetmore. Cedar post surrounded by crockery and tinware." From which 24" Pine stump bears N57°30'W 36'

OCRC WITNESS BOOK 10/23/64 6" Wood Stake with Crockery

P. Pole S30°E Spike T. Maple SW

61.40 40.31

4" Basswood \$45°W

NW

40.25

Spike T Elm

58.7

Unrecorded Survey R. Hepworth # 26457 3-21-88 Fd IR or 1" Bolt

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

I found in the centerline intersection of E-W & N asphalt road and center of gravel road to the south at 2" below surface a 1/2"x5" Bolt. Corner falls in 3'+/- fill section of road in a wet, swampy area. OCRC witnessed corner is probably Salisbury, 1908, corner as description is similar. OCRC witnesse Power Pole is possibly standing but there also exists 1.5' to the north an older, well-rotted Power Pole post w/ bolts into the existing pole which could also be the 1964 OCRC witness. Measurement to the boit is approximately the OCRC witness measurement. All other OCRC witnesses are gone. Upon excavation and removal, no other corner evidence was found.

This Bolt was accepted as the best evidence of the corner and was accepted as being a careful and faithful perpetuation of the original corner. No evidence is known to me that would lead me to believe that the corner should be in another location. I placed a 4"x20" Harrison Cast Iron Monument, stamped "County Surveyor" & "26457" at the found position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

L-7	1/4 Corner Cor	mmon to Sections 13 &	T13N, R17W	Gran	
4"x20" H	arrison Cast Iron	n Monument, stamped '	"County Surveyo	or" & "26457"	
	NW Face	8" Ash	214°az	83.48	EDM
60d spk	N Face	12" B Oak	257°az	147.88	EDM
60d spk	N Face	10" Basswood	286°az	117.12	EDM
20d spk	SW Face	Power Pole	150°az	61.18	EDM

Oceana County Remonumentation

Peer Group Reviewed & Approved 96

J. Randolph Hepworth Oceana County Surveyor

RANDOLPH HEPWORTH LAND SURVEYOR NO. MANAGERED LAN

26457

Surveyor's Michigan License No.

December 5, 1996 Date___

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED JAN., 1983