# SURVEY & EMONUMENTATION

JAN 18 2001

### SECTION

### LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN

COUNTY	UF (	ILLANA
RECEIVED	FOR	RECORD

For corners in	Filing	Requirement of	Act 74, Mich. P.	A. 1970	21 DEC 2000	3:19:01 PM
Oceana	Located In:	Corner Code #			JOSEPH E.	MERTEN
(County)		5511151 5545 #			REGISTER	OF DEEDS
Public Land Survey     Property Controlling in Section     Miscellaneous	T 15NR 1 T 15NR 1 T 14NR 1 T 14NR 1 S T R S T R S T R	7W A-13			1	01017
Property in Sec.	S TR		<del></del>	Reg	gister of Deeds S	tamp & File Number
4. Lot No, Record	ed Plat		·····			
5. Private Claims	· · · · · · · · · · · · · · · · · · ·			1	CDEF	G H I J K L
J. Randolph Hepworth, requirements of P.A. 74, Michigan conformance with regulations and ru United States Department of the Intended that the corner points mentioned in Board of Land Surveyors or by a recovered, found as expressed below	in a field survey on P.A. of 1970, the corner pulses therefore as required reiror, Bureau of Land Manalines 3, 4 and 5 above well Decree of a Court of L	points mentioned in line the current manual of a agement or by a decree te in conformance with i	s 1 and 2 above were survey instructions of of a Court of Law and the rules of the Michie	e in the 5	5 4 9 9 17 16 16 16 16 16 16 16 16 16 16 16 16 16	3 2 1 10 11 -12 -13 -13 -22 -23 -24
NOTE: Not more than 2 comes on this certificate.	s, all in the same town a	nd range, may be rec	orded	9 10-30	29 28	27 26 25
				12 31-	32 33	343536
M-13 CORNER COMMON TO S A-1 SECTION 6 T14N, R17V A-13 SECTION 31 T15N, R17W M-1 SECTION 1 T14N, R18W  GLO John Mullett 1838 SET PC Range 18 & 17 West Book A, Pg. 284, H A Grant, 1891	V SHELBY TOWNSHIP HART TOWNSHIP BENONA TOWNSH  DST Intersected Range 14" Sug	IP IIP e line 45 lks. S. of Tem ar S59°E 9 lks	nporary post & set Pe	ost at intersecti N37°W 54	ions for Cor to Tow 4 lks	ns 14 & 15 North
MDOT Corner Witness J Carlson 1) 25" Maple N68°E		Set 1 1/4" Bar 2) 6" Ash N45°E	59.55'	3) 7" Ash N2	23°W 26.87'	
OCRC Witness Book 1970 Har 1) Maple N70°E 53. 2) 6" Ash N45°E 5	9'	4) 16"Elm N35°E	58.6'	1) 25" Maple	N68°E 54.06'	
MDOT Right of Way Map, File # 6	4-R-2, Pg. 43 1976					
LCRC # 100432, S. Shackelford #X Checks line with old cou 5) 18" Tw Map N66°E 8) 16" Elm West (set)	nty survey of South line : 61.73' (set)	Pipe with parole evider Sec 36:T15N R18W 6) 8" Hickory S76				N 27.27' (set)
Unrecorded Survey, JR Hepworth cap so cap is over point of stone. I found a 1" X 2' pipe about 9' Wes homemade surveying. After tying in 1) 60d spk NW Face	Approx. 10' E of C/L gra t, BUT on verbal stateme	vel road to North and a ent to me on that date n favor of MDSH corne	Approx. 6' N of C/L of Tim Bender, his fa	gravel road to ather, Vic Bend	E and in the C/L of er, probably set thi	gravel Dr. to West. s pipe while doing
9) 60d spk W Face 10) 60d spk NE Face		z 190.03'		Peer Group	nly Remonuments Reviewed & Appr	
11) 50d spk SE Face 12) 40d spk E Face		az 75.60'		Date:	-21-00	<del></del>
13) 60d spk SW Face 60d spk N Face	P Pole 321° 16" Elm 263°			J. Randolph Oreana Com	Hepworth htty Surveyor	
gned by	26457	A Micy of Line	Date		er 15, 2000	

## SURVEY & EMONUMENTATION

JAN 1 8 2001

SECTION

### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

I found a stone with JRH 1/2" Iron and cap bent over the point end of the stone. The 1 1/4" dia. Solid Iron by MDOT was on the north side of the stone about 0.2' below the point of the stone and 0.20' North of the JRH Iron. The stone is pyramidical being 3"x6" at the top and 8"x15" at the bottom and is 24" tall, standing vertical. Witness No. 1, 3, 9 - 13 are all standing and measure OK. The LCRC 100432 witnesses appear as if they are for a different corner than this one as all of the witnesses recited are missing from this site and no apparent reason for being missing is evident to me.

I accept the point of the stone (JRH Iron) as the best available evidence of the position of the original corner rather than the 1 1/4" solid Iron as MDOT surveyor was attempting to point to the stone as the corner. He would have set the 1 1/4" fron as an aid in recovering the stone corner. No evidence other than that recited above is known to me that would lead me to believe the corner should be at another location.

### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 4"x20" Harrison Cast Iron Monument, stamped "County Surveyor" and "26457" in place of the stone. The stone was tipped over northerly of its position.

9) 10) 11) 12)	ex. 60d spk ex. 60d spk ex 60d spk ex. 60d spk ex. 40d spk	NW Face W Face NE Face SE Face E Face	24" Maple Power Pole/transf. 6" Spruce 10" Ash 6" Ash Power Pole	67°az 165°az 143°az 17°az 334°az 321°az	53.84' 190.03' 63.07' 75.56' 24.53' 119.02'	EDM EDM EDM EDM EDM EDM
12) 13)	ex. 40d spk ex. 60d spk set 60d spk	E Face SW Face N Face	6" Ash Power Pole 16" Elm	334 az 321 az 263 az		