STATE OF HICHIGAN COUNTY OF OCEANA RECEIVED FOR RECORD

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

3 DEC 1999 2:14:57 PM For corners in Oceana Located In: JOSEPH E. MERTEN Corner Code # (County) REGISTER OF DEEDS 1. Public Land Survey T14N R18W 100953 R 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. , Recorded Plat 5. Private Claims 1 2 3 i, <u>J. Randolph Herworth</u>, in a field survey on <u>May 20</u>, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the 5 United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or 6 that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 7 8 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 10 1 1. A. Description of original monument and accessories and/or subsequent restoration: I-7 CORNER COMMON TO SECTIONS 14, 15, 22, & 23 T14N, R18W **BENONA TOWNSHIP** GLO J. Mullett 1838 SET POST 18" Beech N70°E (23 lks) 15.2' 12" Beech N11°W (19 lks) Book A, Pg 144; S. Edson, 1882; "One wilness (stump) tree standing and established a corner by burying a stone(bluish in color) about 20 inches long and 12 wide. Book A, Pg 252; E Hyde, 1890; "Found a stone corner previously set." Book A, Pg 264; E Hyde, 1890; "A stone corner previously set." Oceana County Remonumentation Book A, Pg 320; H.A.Grant, 1893; "Stone previously set for Gov't Corner." Peer Group Reviewed & Approved OCRC WITNESS BOOK 1967 Rock & Iron 11-99 1) P Pole , N45°W 72.0' 2) P Pole SE 45° 81.7' 3) Elm N45°E 66.0' 1 pm LCRC #100323, 6/28/84, Fredrick Thompson, # 21996, Fd 1" iron rod in C/L of roads J. Randolph Hepworth 1) P Pole N61°W 71.57' 5) 24" Maple N22°E 80.76' 4) Face Rd Name Sign S56°W 47.15' Oceana County Surveyor 6) P.Pole S73°E 82.28 Unrecorded Survey, JR Hepworth #26457, 8/5/98 Fd 1" Iron 298°az 72.12 7) P. Pole 125°az 59.04' 8) 10" Locust 158°az 89.36' 5) 24" Locust 22°az 80.97 9) 6" Locust 86°az 46.42' B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. I found a 1" solid Iron 8" below the surface and 3' east of the centerline of N-S road and 8' north of centerline of road to the west. The road to the east is

wandering and ambiguous. This corner falls in road intersection in slight cut so it is unlikely that the Edson stone still exists. One OCRC witness is still standing; and three of the Thompson witnesses are standing. Corner is substantially as described by Thompson, 1984. OCRC witnesses probably predates construction of the road to the north; the road to the west as reconstructed in the 1980's.

I accept the Iron as the best available evidence of the position of the original corner. No evidence is known to me that would lead me to believe the corner should be at another location.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

	=			to perpetua	to totatang i	ur boann	m or me c	ormer.	
5) 7) 8) 9) Signed	60d spk 60d spk 60d spk 60d spk 60d spk	W Face W Face N Face SW Face S Face	amped "County Surveyor" and Power Pole/transf 24" Maple Power Pole/transf 10" Locust 6" Locust		" Iron which w 72.13' 80.83' 58.98' 89.30' 46.51'	as driven d EDM EDM EDM EDM EDM EDM	lown.	I. RANDOLPH HEPWORTH LAND SURVEYOR NO. 26457 PED LAND	14,1975 N., 1983