OCT 27 1993

COMMISSION

REMONUMENTATION COUNTY OCEANA LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF OCEANA RECEIVED FOR RECORD

100502

93 OCT -7 P2:45

Foi	r corners in		•
	OCEANA (County)	Located In:	Corner Code ##
1.	· · · · · · · · · · · · · · · · · · ·	T14N R 18W	J-13
1.	Public Land Survey	T R	
		T R T R	
2.	Property Controlling in Section	S T R S T R	
3.	Miscellaneous	S T R	•••••

T R ___

L & meeting REGISTER OF DEEDS

Register of Deeds Stamp & File Number

_ , Recorded Plat __

Private Claims

Property in Sec.

September 30, 191993 J. Randolph Hepworth in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11

Description of original monument and accessories and/or subsequent restoration:

1/4 CORNER SECTION 35 BENONA TWP; T14N, R18W

SET POST GLO

6" BEECH N450W 26.4" 5° BEECH

EDSON, 1880 SET REDDISH STONE 3X10X13 POINT UP WITH CHISELED 'X' AT GLO CORNER

BOOK A-276 GRANT, 1891 STONE PREVIOUSLY SET AT GLO CORNER

BOOK A-224 HYDE, 1889 RED STONE PREVIOUSLY SET (IMPLIED TO BE COMMON WITH 713M & 714M OCRC WITHESS: 1° IROM

SE COR CULVERT HEADWALL N45°W 39.8 T POLE

8" W BIRCH 14.3

49.0 N30°E

54.5

LCRC #100127 J NORDLUND, PS 16345 SET PK NAIL FROM OCRC WITNESS

J-1 N 1/4 COR, SEC 2, T13N, R18W

GUY POLE 47.4 18" ASH HB 61.0 P POLE NW

LCRC #100269 R HEPWORTH, PS 26457 SET 1/2" IRON FROM NORDLUND SURVEY

N 1/4 COR, SEC 2, T13N, R18W

RD NAME SIGN 16.5 16" ASH NW COR SCHOOL HSE 170.15 SW 103.77 SR

B.Description of corner evidence found and/or method applied in restoring or reestablishing corner

RE-ESTABLISHED CORNER BY PRORATING BETWEEN SW & SE CORNERS OF SECTION 35, USING HA GRANT, 1891 SURVEY MEASUREMENTS AND B HOLDING FOR LINE CORNER ACCEPTED AS N 1/4 CORNER OF SEC 2. TI3N, R18W WHICH IS 13.64' EAST. AND IS ACCEPTED AS A CAREFUL AND FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

SOUTH 1/4 CORNER, SECTION 35, T14N, R18W BENONA TOWNSHIP

SET "COUNTY SURVEYOR" HARRISON 4"X20" CAST IRON MONUMENT IN PLACE OF SET 1/2" IRON.

			•		
FOUND 1/2" IRON	713H, R18W CORNER	east	13.64	TAPED	
W EDGE	STOP SIGN	\$35¢ E	53.031	TAPED	
60d SPK SE PACE	POWER POLE	825°W	49.591	TAPED	
60d SPK E FACE	16° ash	s10°W	101.23'	TAPED	
16d SPK SW FACE	GUY POLE	¥25°W	40.591	TAPED	

HEPWORTH LAND SURVEYOR NO.

Signed by

October 6, 1993

Surveyor's Michigan License No. . 26457

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983