STATE OF HICHIGAN COUNTY OF DCEANA RECEIVED FOR RECORD

K.C. 3 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 3 DEC 1999 2:08:18 PM For corners in Oceana JOSEPH E. MERTEN Located In: Corner Code # REGISTER OF DEEDS (County) 1. Public Land Survey T<u>15N</u> R<u>18W</u> 100935 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number , Recorded Plat 4. Lot No. 5. Private Claims 1 2 3 I,J. Randolph Hepworthn a field survey on October 1,49 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or 5 6 that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan 7 Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 8 NOTE: Not more than 2 corners, all in the same town and range, may be recorded a on this certificate. 11 A. Description of original monument and accessories and/or subsequent restoration: F-7 1/4 CORNER COMMON TO SECTIONS 16 AND 21 T15N, R18W **GOLDEN TOWNSHIP** J. Mullett 1838 SET POST 9" Birch N17°E (23 ks) 15.2' 15" Birch S55°W (23 lks) 15.2' Book A, Pg. 200, EM Hyde, 1888; "Found one original witness tree and an iron corner." Book A, Pg. 360, H.A.Grant, 1894; "See No. 15 Page 201." Oceana County Remonumentation Peer Group Reviewed & Approved OCRC Witness Book Pre-1965 Flat Boiler Plat Fence Cor NE Cor Woods 11-11-99 1) Tw 10" Maple WSW 57.8" SW 18.9' SW 45.6' 2) 30" Maple J. Randolph Hepworth Oceana County Surveyor Unrecorded Survey, JR Hepworth #26457, 2/27/84, Fd Lakestate ½" IR beside Lg Iron Inters Fences E-W & S 42" Maple 237°az 19.70 3) 36" Oak 4) 12" Maple 205°az 46.27 South 13.51 12" Tr. Cherry East 54.36 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. I found a Lakestate Survey 1/2' Iron & cap at the Intersection of old occupation lines E – W & S at the Northeast corner of the woods. No occupation is visible to north across an open field. All four JRH, 1984 witnesses are standing and measure OK. All OCRC pre-1965 witnesses are standing and measure OK. The Lakestate Iron was found to be directly beside a piece of cast iron plate 1/8"x6"x8". It is unfortunate that Hyde, 1888, did not describe the "iron comer". Upon excavation, I found well-rotted remains of a wood post beginning about 16" below the surface. Perhaps this plate is the Hyde corner and the rotted post is the remains of a corner fence post.. I accept the Iron and plate as the best available evidence of the position of the original corner. No evidence is known to me that would lead me to believe the corner should be at another location. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 4"x20" Harrison Cast Iron Monument, stamped "County Surveyor" and "26457" above the 1/2" Lakestate Iron which was driven down; I placed the cast iron plate material in the hole beside the monument.

1) 60d spk N Face 1 14" Maple 260°az 58.21 **EDM** 60d spk NW Face 48" Maple 237°az **EDM** 19.76 60d spk W Face 12" Maple 187°az of MICHIGAN 13.66 **FDM** 60d spk S Face 4" Maple 39.65 **EDM** S Face 60d spk 10" Cherry 273°az 39.61

Signed by

Surveyor's Michigan License No.

26457

FORM APPROVED BY MICHIGAN STATE BOARD ON PROVESSIONAL SURVEYORS, JAD. 28, 1971

LANAEVISED JAN., 1983
REVISED JAN., 1983
REVISED OCT., 1996 REGISTA

Date November 30,

I. RANDOLPH HEPWORTH

LAND