SURVEY & REMONUMENTATION

JAN 11 1999

100844 STATE OF NICHIGAN

COUNTY OF OCEAHA

SECTION

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

Oceana			1	ZB DEC 1998	4:30:18 PM
(County)	Located In:	Corner Code #		JOSEPH E.	. MERTEN
1. Public Land Survey	T ^{15N} R ^{17V} T15N R _{16V} T R			REGISTER	OF DEEDS
Property Controlling in Section Miscellaneous Property in Sec.	TR_ S TR_ S TR_ S TR_ S TR_		Regis	ster of Deeds Stan	on 2 Cilo Number
4. Lot No, Recor	ded Plat				ih et tile Mnube
F. Randolph Hepwort requirements of P.A. 74, Michiga conformance with regulations and United States Department of the in that the corner points mentioned	h, in a field survey on May n P.A. of 1970, the corner pol rules therefore as required in the interior, Bureau of Land Manage in lines 3, 4 and 5 above were as Decree of a Court of the corner of a Court of the cou	8, 1998 10ts mentioned in lines 1 and 2 above the current manual of survey instructive ement or by a decree of a Court of La in conformance with the rules of the cy; established, re-established, mon	/e were in ons of the aw and /or 6 18 18 18 18 18 18 18 18 18 18 18 18 18	C D E F G	H I J K L 3 - 2 - 1 10 - 11 - 12
NOTE: Not more than 2 come on this certificate.	ers, all in the same town and	I range, may be recorded	8 19 9 10 30 11 12 31	-20 -21 - 2 -29 -28 -2 -32 -33 -36	7 26 25 4 35 36
Book A, Pg 51; S, Edson: 1879	D SECTION 13 T15N, R1 R16W ELBRIDGE TOWNS 12" Beech S60°W 17.8	17W HART TOWNSHIP SHIP 3' 10" Sugar N41°W 23.8'	Date:	na County Remonus Group Reviewed &	Approved
Book A, Pg 208; E. Hyde, 188 around it." Book B, Pg 44; F. Wetmore, 180 Book C, Pg 40; F. Wetmore, 180 Book A, Pg 20; H. Selisbury, OCRC WITNESS BOOK 32.2' N. W. to Cent	1903; Corner not described or w 1903; Corner not described 1905; Corner not described 1908; Corner not described 1908; Corner not described	vitnessed t and both witnesses and set blue a or witnessed. I or witnessed. d or witnessed. tor witnessed. tones and crockery	J. Ran	dolph Hepworth 12 by 35 inches with	earthen
		nethod applied in restoring o			
I found in the centerline of a N-	S Dirt Trail and on a Poplar to	ree and Field occupation lines E-W of a blue-white speckled granite si ound to be approximately 8"-12" sq	a 1/2" Pipe on the sout	th side of a large stor	ne. Upon ling vertical cribed by
l accept the stone crockery and	i pipe as a careful and faithfu	Il perpetuation of the position of the			
C. Description of monume	ent for corner and access				

er and accessories established to perpetuate locating the position of the corner.

19.65 EDM EDM EDM 6" Poplar 12" Poplar 6" Box Elder 36°az 270°az 22.76 60d spk S Face 60d spk W Face 60d spk E Face 61.64 173°az 87.12 **EDM** 60" Elm clump 137.45 EDM

Signed by Surveyor's Michigan License No.

November 10, 1998

J. Randolph HEPWORTH LAND