SURVEY & REMONUMENTATION

JAN 11 1999

SECTION

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

10085
STATE OF AICHIGAN
COUNTY OF OCEANA
RECEIVED FOR RECORD

28 DEC 1998 4:31:36 PM

Oceana	Located In:	Corner Code	e#				10	SEPH	E. M	ERTEN		
(County)								GISTE			ĵ	
1. Public Land Survey	TR TR						•					
2. Property Controlling in Section	g SR											
3. Miscellaneous	SR										•	
Property in Sec.	ST_R					Regist	er of E)eeds	Starr	1 p & F	ile Nu	ımbe
4. Lot No, R	ecorded Plat											
5. Private Claims					1 A	<u>B</u>	C D	E F	G	HI		K L
					2	6	 	- 	+	3-+	ģ	
.J. Randolph Hepm	worth P	pril 28, _19	98.		3 -	+		+	+	+	_	++
I.J. Randolph Hepworth, in a field survey on April 28, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in					4	-7 	 - 8 -	9. 	\top	10-	11	12 1
conformance with regulation	s and rules therefore as require	d in the current manu	al of survey instruction	ons of the	5	1	- -	•		11		$\dagger \dagger$
that the corner points ment	f the Interior, Bureau of Land N ioned in lines 3, 4 and 5 above	were in conformance	with the rules of the	Michigan	6	18 	17- 	16- 	_	15	14 	13
Board of Land Surveyors recovered, found as express	or by a Decree of a Court of ed helow:	f Law; established, i	re-established, mon	umented,	7 -	<u> </u>					1	
•					. 8 -	<u> </u>	1	1		1	_23 ·	
NOTE: Not more than 2 on this certificate	comers, all in the same tow	n and range, may b	e recorded		9 -	30	10	28		<u> </u>		
on the ocidioate	•							20			2 6	ĽΪ
E-5 CORNER CO	MMON TO SECTIONS 8, 9,	16 and 17 ELBR	IDGE TWP; T15N	I, R16W	11	_ 31	32	33	_	34	_35	36
■ GLO -Set Post - 6"	Reech S31°F 46.5' .	6" Beech	V62°W . 14.5'		13		LI					
	Prochument and Sciessori	•	ent restoration;									
Book A, Pg 78; S. Eds	on, 1880; Corner not describ	ed or witnessed					_	_				
	ed; 3/8"x 1 1/2" Iron; 12" M onc Porch of Store 42.5' (no		SE Cor of Church	n 66.35' (n	o dir	recited	Peer (roup	Revie	ewed &	& App	roved
HEPWORTH, PS, 4-1983, unrecorded survey; Found 3/8"x1 1/2" Iron Center of Road Intersection 18" Maple NE 54.26 NE Cor BLDG SW 47.4 Rd Name Sign SE 37.9 20" Maple ENE 102.45					Date: 10-13-98 J. Randolph Hepworth							
B. Description of co	orner evidence found and	or method applied	l in restoring or	reestablish	ing c	orner	A		•		or	
witness to a 12" Maple probably the OCRC cor	on Bar (piece of Leaf Spring) is still standing and measures mer and is accepted as a care construction. After new road	s consistent to OCRO	 The other OCF etuation of the posit 	ion of the o	s are riginal	gone. corne	r. 1	he 3/8' The Iro	" x 1 1 n Bar	/2" Iros was te	n Bar i: empora	is arily
C. Description of r	nonument for corner and	accessories establi	ished to perpetua	ite locating	g the	positi	on of t	he cor	ner.			
Set "County Surveyor" PK Nail N Face 40d spk	MMON TO SECTIONS 8, 9, Harrison 4"x20" cast iron mor Power Pole 20" Maple		ounty Surveyor" and 96.63 102.42	d "26457" in EDM EDM	place	of fou	ınd 3/8"	x 1 1/2	!" iron	bar		
40d spk SE Face PK Nail W Face NE Corner, Concrete P NW Corner, Concrete F PK Nail	18" Maple Power Pole Forch at NE corner of Bldg Porch at top of conc.	45°az 44°az 218°az 121°az south	65.95 E 48.85 E 103.66 E	EDM EDM EDM EDM EDM			SIAT	of I		•		ļ
>				,			REGION A	LA SURV	ND EYOR O.		ADJ. HOL	f f r *
							all phi	WHILE F.	HIAN		-	

November 10, 1998

Date

26457

Surveyor's Michigan License No.