REMONUNATION

MAY 1 8 1997

STATE OF MICHOAN COUNTY OF COEMAC RECEVED FOR PARTY

	ONTHE FILING Filling	Requirement of Act		70 '96 DEC 19	A11 :14 10072
For corners in Oceana (County)	Located In:	Corner C	Code #	Jung L	Meter
1. Public Land Sur	T	R R		REGISTER OF L	A.EOS
Property Contro in Section Miscellaneous Property in Sect	T Illing S T S T	R R R		Register of Deeds Sta	amp & File Number
	, Recorded Plat			A B C D E	FGHJK
5. Private Claims _	<u> </u>			2 6 5	9 10 11
do hereby certify that in lines 1 and 2 above manual of survey in Management or by a 5 above were in confidence of a Court of I	under requirements of P.A. 74, Mi were in conformance with regulat structions of the United States decree of a Court of Law and/or tormance with the rules of the Mi Law; established, re-established,	ichigan P.A. of 1970, the co tions and rules therefore as a Department of the Intel that the corner points menti ichigan Board of Professio	orner points mentioned required in the current rior, Bureau of Land tioned in lines 3, 4 and anal Surveyors or by a	7 8 19 20 20 20 20 20 20 20 20 20 20 20 20 20	21 22 23 2 28 27 26 2
as expressed below: NOTE: Not more the on this cert	nan 4 corners, all in the same sificate.	town and range, may be	recorded	11 2 31 32	33 - 34 - 35 - 3
G-6 1/4 Corn	original monument and accer er Common to Sections 1	5 & 16 T15N, R16W	Elbridge Town	nshìp	
	Edson, 1879; "Beginning in the C		was established from		
OCRC WITNES	cl. of Basswood W. 57.60'	ground and over which a gra 1 1/2" Gas pipe set on top o "V" hash in 20" Maple S5°E 35.4' 8" Maple N25°I	of iron E 67.2'	about 20 inches long, 8 wid	le and 6 thick."
LCRC# 100423, R Clp 10" A		Fd Large Iron, raised with 1/ Tw 18" Maple 3	/2" X 2' Iron 31°AZ 126.56'	8" R Pine	150°AZ 106.66'
B. Description	of corner evidence found and	l/or method applied in	restoring or reesta	ablishing corner.	
fence post and bar found to be 26" lon	Iron and cap as described in LCR b wire fence to the east. Upon ex g with a 1/2"x1"x16" iron inside an cient to accept this position.	cavation and removal, it wa	as found to be a riser fo	or an 1-1/4" Pipe at 14" de	ep. The Pipe was
the original corner	and 1-1/4" pipe was accepted as . No evidence is known to me tha a 4"x20" Harrison Cast Iron Monu	at would lead me to believe	that the corner should	be in another location. T	he pipe was driven
C. Description	of monument for corner and	accessories established	l to perpetuate loca	ating the position of th	ie corner.
	•	T15N, R16W nty Surveyor" & "26457" 266°az 233°az 146°az 21°az 176°az north	Elbridge Township TV 58.00 EDM 57.48 EDM 106.68 EDM 126.53 EDM 614.04 EDM 2635.30 EDM	I. RANDO HEPWOR	ATH A S

Manufactures -

THE J. Randolph Hepworth Oceana County Surveyor

Date:

Oceana County Remonumentation

Peer Group Reviewed & Approved

Surveyor's Michigan License No. 26457

Date December 5, 1996

FORM APPROVED BY MICHIGAN STATE SOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1963