

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION


LAND CORNER RECORD

T. 16 N.R. 15 W

OCEANA COUNTY

DESCRIPTION OF CORNER N 1/4 Corner Section 3
CORNER MONUMENT Found 5/8" rod in T road. Inter. (N-E-W) & centered on old road to S.
DATE MONUMENT PLACED AND WITNESSED April 1969

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

Fd. scribed 8" Ced (Twin) cut off	S 40 W	53.6'
Fd. 10" scribed Cedar	N 68 W	50.8'
AND Fd. Nail in NW Side P. Pole	S 43 W	43.5'

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered from data furnished by George Blass, RLS Baldwin, and Bob Griffin, Forest Service, Baldwin. See Report of Survey & Plat of Survey, Sec. 3, T16N-R15W.

SURVEYOR'S SEAL

SIGNED

Paul F. Rosen
REGISTERED LAND SURVEYOR 12028

DATE

April 1969