MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 16 N.R. 15 W

					OCEANA			COUNTY		
DESCRIPTION OF CORNER _	SEC. CORNER CO	MON	TO SECTION	S 2-3-1	10-11			·		
CORNER MONUMENT							Mon.	& Ced.	Guard	Post
DATE MONUMENT PLACED AN	D WITNESSED	Apr	11 1969							
WITHESSES TO CORNER	9"	Red	Pine		S 75	W		24.1		
N	7"	Red	Pine		S 25	<u>w</u>		15.6'		
3	01	d E-1	W Fn. Remai	ns l	Due N			15.0		
CIRCLE CORNER REGISTER	AND									

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

THIS CORNER WAS RECOVERED DURING RETRACEMENT AND BOUNDARY SURVEY IN THIS AREA.

THE CORNER WAS FOUND FROM WITNESS FURNISHED BY BOB GRIFFIN, RLS, FOREST SERVICE,

BALDWIN. THE CORNER IS BELIEVED TO BE A SALISBURY CORNER. SEE REPORT OF SURVEY

AND PLAT OF SURVEY, SEC. 3, TIGN-RISW.

SURVEYOR'S SEAL

SIGNED LAND SURVEYOR 12028 DATE 5/27/69