SURVEY & REMONUMENTATION

APR 2 5 1995

Surveyor's Michigan License No.

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN COUNTY OF CICENNA RECEIVED FOR PERIORD

COMMISSION For corners in		Filing Requirement of Act 74, Mich. P.A. 1970					JAN -	4 P3	.24		
OCEANA (County)	Loc	ated In:	. Corr	ner Code ##		June		F DEEDS			
Public Land Survey	τ. Τ.	L6N_ R _1.5W_ R R		E-8		, RE	er i er i	P DEEGG			
Property Controlling in Section Miscellaneous	S T . S T . S T .	R R R			Regi	ster of D	eeds S	tamo & F	File Nur	nber	
Property in Sec.	s r	R									_
4. Lot No, 5. Private Claims						2 A B	C D 1	F G	H J	K L	
J. Randolph Hepword, and hereby certify that under rein lines 1 and 2 above were current manual of survey insumanagement or by a decree cabove were in conformance of Court of Law; established.	, in a field sur equirements of P., in conformance tructions of the U of a Court of Lawai with the rules of th	with regulations ar nited States Depar nd/or that the corn re Michigan Board	, of 1970, the nd rules the rtment of the er points me of Land Sur	e corner points me erefore as require e Interior, Bureau entioned in lines 3, veyors or by a Dec	ntioned d in the of Land , 4 and 5 cree of a	3 4 7 5 6 18 7 8 19 9	-1720	-16	101	1 12 4 13 3 24	
expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded						10	29	28	27 2	625	_
on this certificat						13 31	32	3/3-	34-3	536	
A. Description of origina E-8 1/4 CORNER COMMO					on:						
GLO SET POST 12" Bo	eech N50°W 15.	2' 10" Ma	ole S34°E	18.5'							
USFS, R. Griffin, PS, 1975; Cedar Stake. 4" B Oak West 53. 8" S. Maple S45°E	.28	pavement centerling 24" Pine Stump 24" Pine Stump	ne. Locatio S43°W S45°W	65.12	vitnesses SW. 2" B Oak		a old fend 9°W 7		HC Salis	bury, 193	32
No other historical records are	known to me.										
B. Description of corner of	evidence found a	nd/or method ap	plied in res	storing or reestal	olishing corne	er					
I found a 1/2" Iron 3" below the north of E-9 corner. Area t not visible. No occupation li Origin of this 1/2" Iron is unkno	o southwest has be nes are distinctly v	een heavily timbere isible; but, this is ap	d in recent y oproximate I	ears. About 150	asures 2658.35 ' east, I could d n land use to th	etect sma	Corner E Il pieces	E-7; and m of old barl	easures b wire of	2625.39' old fence	;
No evidence is know to me the FAITHFUL PERPETUATION					tion. The 1/2"	lron is AC	CEPTE	OAS A CA	AREFUL	AND	
C. Description of monun	nent for corner a	nd accessories es	tablished t	o perpetuate loca	ating the posi	tion of th	e corne	r.			
E-8 1/4 CORNER COMMO SET "COUNTY SURVEYOR"	HARRISON 2 3/4"	X20" CAST IRON N	MONUMENT		e found 1/2" iro	n	,				
60d spk N Face	3" W Oak 6" B Oak 8" Sassafras 50" Maple 8" Cherry	233°az 272°az 332°az 96°az 151°az	51.28 53.03 89.09 113.26 123.52	EDM EDM EDM EDM EDM		* *	HE	MICH ANDOLPH PWORTH LAND	Control		
			Peer Date:	ndorph Hepworth	& Approved	William Control	PEREL	JRVEYOR NO. 26457 D LAND		Nike.	
	Pal		Ocea	na County Surve	yor						

November 7, 1994

Date