Oceana County Remenum	nentalian SURVEY &		<u> </u>
Peer Group Roviewed &	ApproREMONUMENTAT	TION	STATE OF MICHIGAN
Date:			COUNTY OF COLORA
J. Randolph Hepworth	——— APR 2 5 1995 LAND COR	NER RECORDATION CERTIFICA	TE 100578
Oceana County Surveyor	COMMINISTRA	airement of Act 74, Mich. P.A. 19	785 JAN -4 P3:24
For corners in OCEANA	@ @ 1 4 10 A 16 @ @ () 1	,	
(County)	Located In:	Corner Code ≠	and E. Millians
4 5 40 4 40	T16 D18		REGISTER OF DEEDS
Public Land Survey	T <u>16N</u> R <u>15W</u> T R		
	T R		
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	T R		
2. Property Controlling in Section	S T R		
3. Miscellaneous	S T R		Register of Deeds Stamp & File Number
Property in Sec.	\$ T R		
4. Lot No	, Recorded Plat		- ABCDEFGHIJKIM
5. Private Claims			A B C D E F G H I J K L M
			3 5 4 3 2 1 1
J Randolph Henwo	rth Sont	combor 1 1994	4 7 8 9 10 11 12
do hereby certify that under	, in a field survey on	ember 1, 1994 . 19	5
In lines 1 and 2 above were	e in conformance with regulations	and rules therefore as required in the	6 18 17 16 15 15 14 13 1
Management or by a decree	structions of the United States Dep of a Court of Law and/or that the co	partment of the Interior, Bureau of Land rner points mentioned in lines 3, 4 and 5	7
above were in conformance	with the rules of the Michigan Boar	d of Land Surveyors or by a Decree of a re-monumented, recovered, found as	9 20 21 22 23 24
expressed below:			10 -30 -29 -28 -27 -26 -25
NOTE: Not more than 4 on this certifical	corners, all in the same town	and range, may be recorded	
on this certifica	te.		12 31 32 33 34 35 36
	al monument and accessories a TO SECTIONS 32 and 33 T16N,R		
GLO SET POST 8" Bee	ech N75°E 33.0' 8" Su	ıgar N50°W 35.0'	
OCRC Witness Book: 5-14-51		R15W corner, No witnesses recited.	
		witnessed; 45.83' West of T15N corner- F	iound existing from relead with T from
Consumors Forest Co., C. Die	193, 1990, Collies that described of t	Millessed, 45.05 West Of 115M Colliel- 1	ound existing non raised with 1 non.
B. Description of corner	evidence found and/or method a	pplied in restoring or reestablishing c	corner
centerline projection of the as	pk inside at the centerline projection sphalt road to the South is 46 feet ea T Iron 45.80' East at recorded positio	st. Upon removal of the 1" Pipe, it was fo	centerline of an east-west gravel road. The ound to be above a 2" Pipe 16" below the surface of
No evidence is known to me t	that would lead me to believe that the	corner should be at another position.	
		RPETUATION OF THE POSITION OF THE	CODICINAL CORNER
C. Description of monun	nent for corner and accessories	established to perpetuate locating the	position of the corner.
E-13 CORNER COMMON	TO SECTIONS 32 and 33 T16N,R	15W COLFAX TWP	
SET "COUNTY SURVEYOR" 60d spk NW Face	HARRISON 4"X20" CAST IRON MC 8" Maple 259°az	NUMENT above the found 1" Pipe and ab 115.70 EDM	pove the 2" Pipe
60d spk N face	20" Tw Cherry 253°az	74.55 EDM	
40d spk SW Face PK Nail SW Face	Power Pole 307°az Power Pole/transf 159°az	98.40 EDM 208.56 EDM	
T15N, R15W corner	East	45.80' EDM	
			The said of the sa
			of MICH/S
			S. r. J. RANDOLPH
			ation SURVEYOR CO
		Oceana County Remonument Peer Group Reviewed & Appr	roved Was Survivor 15 2
		Date: 8-18-94	NO. 26457
		JKH -	MILERED TAND SU
		J. Randolph Hepworth Oceana County Surveyor	Manne
. //	/ul /		
	/// Here of		
Signed by	26457	DateNo	vember 7, 1994
Surveyor's Michigan Lice		Finale &	PPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

VEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983