(2)

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

| FOR CORNERS OF–: | LOCATED IN–: | CORNER CODE NUMBER |
|---|---|---|
| 1. PUBLIC LAND SURVEY | T. 16 N., R. 18 W. | I-11; I-12 |
| 2. PROPERTY CONTROLLING IN SECTION 35 | ,T. 16 N., R. 18 W. | 3; 10 |
| 3. MISCELLANEOUS PROPERTY IN SECTION | ,T. N. S., R. E. W. | |

4. LOT NO. _____ , RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Sept. 25, 19 78, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (continued) 10

Set 5' steel fn. post &
Ced.Post w/Loc. Tag

| | | |
|---|---|---|
| 6" Hemlock | N20°W | 30.4' |
| 4" Maple | N20°E | 5.4' |
| 16" R.Oak | S60°W | 33.7' |
| N-S Rand. | Due W. | 1.2' |

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-11 Recovered and accepted 3/4" Pipe; probably by S. Barnett as it fits his survey of Sec. 35. Corner falls in approx. intersection of Trail Roads N-S-E-W.

I-12 Fd. & accepted 3/4" pipe per RLS, Sam Barnett survey of Sec. 35. There is smooth wire on trees (not straight) to South & East.

3 Fd. & accepted angle iron, by S. Barnett per his survey of S-35.

10 Estab. 1/16 Cor. per Std. B.L.M. Instructions. Cor. of smooth wire on trees(E'ly&N'ly) is 25'±E.&71'±S.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

| I-11 | | | I-12 | | | 3 | | |
|---|---|---|---|---|---|---|---|---|
| Fd. 3/4" pipe | | | Fd.3/4" pipe; added DNR | | | Fd.3/4"X3/4"X18" Angle iron; | | |
| 18" Twin W.Oak | N35°W | 29.43 | Mon.& Ced.Post | | | added Ced.Post w/Loc. Tag | | |
| 22" W.Oak | S65°E | 49.17 | 9" Maple | N03°E | 29.39 | 12" W.Oak | N60°E | 14.7 |
| Set Ced.Post w/Loc.Tag | | | 16" Maple | S75°E | 7.73 | 7" B.Oak | S10°W | 10.5 |
| | S45°E | 47' | 6" W.Birch | S20°W | 17.48 | Fd.3/4"X3/4" | | |
| | | | | | | Angle iron | Due E | 33' |
| | | | | | | Ctr. N-S trl. | Due W | 15'± |

SIGNED BY Carl F. Roser 10-2-78 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN — CARL F. ROSER — LAND SURVEYOR — No. 12028 — REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

PENTWATER TOWNSHIP
OCEANA COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET