Oceana County

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 16 N. S., R. 18 E. W.	J-11;K-11;L-11;M-11
2. PROPERTY CONTROLLING IN SECTION 35	T. 16 N. S., R. 18 E. W.	1
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	

4. LOT NO. _____, RECORDED PLAT _____

5. PRIVATE CLAIMS _____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Sept. 25, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration

C. (continued)

M-11

Fd. 1 1/2" pipe; added Ced.Post w/Loc. Tag

8" W.Pine	S45°W	33.08
10" W.Cherry	Due N	34.30
9" W.Cherry	N60°E	36.38

1

Fd. 3/4"X3/4" Angle Iron; added Ced.Post w/Loc. Tag

Ctr. E-W Dirt Rd.	Due N.	16'+
14" R.Oak	N10°E	4.5'
5" R.Oak	Due W	11.0'
Fd. Old Well point (buried 1')	N20°21'W	14.6'
Fd. 3/4"X3/4" Angle Ir.	Due S.	33'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

J-11 Fd. & accepted Conc. Mon w/Brass Cap. by RLS, C. Cole.
K-11 Fd. & accepted Conc. Mon. w/Brass Cap by RLS, Geo. Blass.
L-11 Fd. & accepted 2" pipe in approx. ctr. of N-S dirt trail. Corner has recently been used and witnessed by others.
M-11 Fd. & accepted 1 1/2" pipe as previously tied-in and witnessed by M.S.H.D.
1 Recovered angle In. by RLS, Sam Barnett; equidistant and on line between 1/4 Cor. E. and Sec. Corner W.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-11

Fd.brass capped conc. Mon., added Ced.Post w/Loc.Tag

12" R.Oak	N15°W	41.72
5" W.Pine	S45°E	43.39
14" R.Oak	S45°W	24.14
Ctr. Crooked dirt trail	E-W N.	26'±
Ctr. Crooked dirt Trail	N-S E.	37'±

K-11

Fd.brass capped Conc. Mon. & added Ced.Post

6" W.Oak	N75°W	28.44
11" B.Oak	N70°E	24.16
14" B.Oak	S25°W	23.83

L-11

Fd. 2" pipe

13" R.Pine	N35°E	32.30
9" W.Oak	S85°E	37.09
11" B.Oak	S30°W	39.90
Set Ced.Post w/Loc.Tag	Due W	33.0

SIGNED BY Carl F. Roser 10-2-78 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN CARL F. ROSER LAND SURVEYOR No. 12028 REGISTERED LAND SURVEYOR (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR

PENTWATER TOWNSHIP
OCEANA COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET