LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF–:	LOCATED IN–:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 16 N., R. 18 W.	I-11; I-12
2. PROPERTY CONTROLLING IN SECTION 35	T. 16 N., R. 18 W.	3; 10
3. MISCELLANEOUS PROPERTY IN SECTION ____	T. ____ N. S., R. ____ E. W.	
4. LOT NO. ____ , RECORDED PLAT ____		
5. PRIVATE CLAIMS ____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Sept. 25, 19 78, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (continued) 10

Set 5' steel fn. post &
Ced.Post w/Loc. Tag.

6" Hemlock	N20°W	30.4'
4" Maple	N20°E	5.4'
16" R.Oak	S60°W	33.7'
N-S Rand.	Due W.	1.2'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

I-11 Recovered and accepted 3/4" Pipe; probably by S. Barnett as it fits his survey of Sec. 35. Corner falls in approx. intersection of Trail Roads N-S-E-W.

I-12 Fd. & accepted 3/4" pipe per RLS, Sam Barnett survey of Sec. 35. There is smooth wire on trees (not straight) to South & East.

3 Fd. & accepted angle iron, by S. Barnett per his survey of S-35.

10 Estab. 1/16 Cor. per Std. B.L.M. Instructions. Cor. of smooth wire on trees(E'ly&N'ly) is 25'±E.&71'±S.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

I-11

Fd. 3/4" pipe		
18" Twin W.Oak	N35°W	29.43
22" W.Oak	S65°E	49.17
Set Ced.Post w/Loc.Tag		
	S45°E	47'

I-12

Fd.3/4" pipe; added DNR		
Mon.& Ced.Post		
9" Maple	N03°E	29.39
16" Maple	S75°E	7.73
6" W.Birch	S20°W	17.48

3

Fd.3/4"X3/4"X18" Angle iron;		
added Ced.Post w/Loc. Tag		
12" W.Oak	N60°E	14.7
7" B.Oak	S10°W	10.5
Fd.3/4"X3/4"		
Angle iron	Due E	33'
Ctr. N-S trl.	Due W	15'±

SIGNED BY Carl F. Roser 10-2-78 DATE ____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ____ DATE ____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY ____ DATE ____
MICHIGAN REGISTERED LAND SURVEYOR

STATE OF MICHIGAN
CARL F. ROSER
LAND SURVEYOR
No. 12028
REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. ____

PENTWATER TOWNSHIP
OCEANA COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1978

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET