## SURVEY & REMONUMENTATION

APR 2 5 1995

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF DICEARA RECEIVED FOR BUILDING 100573

JAN -4 P3:24

For	r corners in		<del>-</del>	•			
	OCEANA		1		i		
	(County)		Located In:	Corner Code =##	1	Jungle & Martines	
						REGISTER OF DEEDS	
1.	Public Land Survey		T16N R16W	E-9		MESISTER OF CEROS	
			T R				
			T R				
_		_	T R			San	
2.	Property Controlling	S	T R			•	
	in Section	S	T R	<u> </u>			
3.	Miscellaneous	S	T R		Box	winter of Donds Clause & File No. 1	
	Property in Sec.		T R		Lec	gister of Deeds Stamp & File Number	
4.	Lot No,	Recorded	Plat	***************************************			
5.	Private Claims				<del></del>	ABCDEFGHIJK	
						2 6 5 4 3 4 2	
						3 1 1 1 1 1 1	
т	Randolph Henro	rth .	Contomb	1 100 <i>4</i>		4 - 7 - + 8 - + 9 - + 10 + 11 - +	
1, =	· randorph hepwo.	∸, —in a fie	id survey on September	er l, 1994 , 19 _		5	
dol	nereby certify that under re	quirement	s of P.A. 74, Michigan P.A. c	f 1970, the corner points me	entioned	6 18 17 18 15 14	
ın ı	ines 1 and 2 above were	in conform	ance with regulations and	rules therefore as require	d in the	10 1 - 17 - 10 - 1 - 14 - 1	
cur	rent manual of survey inst	ructions of	the United States Departr	nent of the Interior, Bureau	of Land	7	
Mai	nagement or by a decree of	aCountor	Law and/or that the corner	points mentioned in lines 3	, 4 and 5	8 19 20 21 22 23	
apo	ove were in conformance w	ith the rule	s of the Michigan Board of	Land Surveyors or by a Dec	cree of a	9	
	oressed below:	re-establis	inea, monumentea, re-m	onumented, recovered, fo	ound as		
-						10 30 29 28 27 26	
NO			ill in the same town and	d range, may be recorde	ed	11	
	on this certificate	١,				12 31 32 33 34 35	
						13 1 1 1 1 1 1	
A.	Description of original	monumei	nt and accessories and	or subsequent restorati	on:		
	E-9 CORNER COMM	ON TO SEC	CTIONS 20, 21, 28, AND 29	T16N, R16W CRYST		liP	
			, , ,			•••	
	GLO SET POST 8	"Beech N	32°W 21.1' 6" Beed	h S20°E 14.5'	(	Öcëana County Remonumentation	
					ı	Peer Group Reviewed & Approved	
	Book A, Pg 238; E. Hyde		'Found a stone corner previ		•	Date: 8-18-94	
	Book A, Pg 350; H.Grant		Corner not described or witn		1	Datei	
	Book B, Pg 14 , F. Wetm		Corner not described or w			1KH	
	Book C, Pg 12, F. Wetmo	ore, 1900;	Corner not described or v	vitnessed.	:	Kandolph Hepworth	
	OCRC WITNESS: 196	9. IRON	,			Oceana County Surveyor	
	Apple S45°E 61		P.P. N45°E 79.30	4" W. Chorne Duo No			
	71ppio 040 E 01	.00	F.F. 1440 E 79.00	4" W. Cherry Due No	JIII 127.10		
	Consumers Power Co., G	. Blass, 19	68; Found Well Point, raise	ed w/T Iron			
	18" Maple S7	3°E 96.11	Power Pole i	N28°E 79.21	cor F	Fence Post S10°W 29.91	
	Act 132 Suprov: Nordlung	1 D046345	2 22 76 Jack H. 476. /				
	establishing this corner w	llund, PS16345,  3-23-76, Jacket No 176; Corner labelled as "Set", but was not der was not recited				ibed. Method of replacing or re-	
	Nail in PP N2		Fence Post I	Oue S 34 24			
				300 0 1127			
			er witnessed for OCRC for F	Road Construction Fd.	1/2" iron		
	P Pole/Transf 25° az 66	5.99'	P.Pole 122° az 103.5	9' <b>3" Cherry</b> 1	198° az 59.05	3" Cherry 240°az 98.55	
						·	
	B. Description of corner evidence found and/or method applied in restoring or reestablishing corner						
	or Blass witnesses are st	w the surfac	the Needland Dames Dal	rest gravel road and in the or	enter of faint &	overgrown track to the North. No OCRC	
	this is the corner establish		The Nordiung Power Poli	witness is standing and me	easures good t	to the 1/2" Iron which makes me believe that	
	ting is the corner establish	ned by Norc	nuna iii 1970.				
	Further search of the area	a failed to v	ield any other evidence for	a conflicting position for the	corner Th	nis represents the best available evidence for	
	the position of the corner.	The	Found 1/2" Iron IS ACCEF	TED AS A CAREFUL AND	FAITHFUL PE	RPETUATION OF THE POSITION OF THE	
	ORGINAL CORNER.				, , , , , , , , , , , , , , , , , , , ,		
				·			
	C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.						
	at Movember						
	E-9 CORNER COMM	ON TO SEC	CTIONS 20, 21, 28, AND 29	T16N, R16W CRYST	AL TOWNSH	IP CONTRACTOR	
	SET "COUNTY SURVEYOR" HARRISON 4"X20" CAST IRON MONUMENT above the found 1/2" Iron						
	321,330HT 00KVET	ALL HAIVU	COLL YER OVER INOISE	UCHONIEM BOOMS HIS IOUN	u 1/4 11011	J. RANDOIDH	
	16d spk/cap NW F	ace	Power Pole/Transf	25° az 6	6.99' Tape	HEFWORTH 4	
	60d spk NW F	ace	Power Pole		03.59' Tape	LAND : 2	
	center		3" Cherry		9.05' Tape	SURVEYOR Q	
	center		3" Charne	240° 0	9 55' Tono	Maria No. 120 A	

Date November 7, 1994 26457 Surveyor's Michigan License No. \_ FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983