SURVEY & REMONUMENTATION

JUN 0 2 1994

OGEMAW COUNTY REMONUMENTATION

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

| RECURDED |
|-------------------|
| OCENTA COUNTY HIS |

LABER

2 PAGE 228

For corners in

Filing Requirement of Act 74, Mich. P.A. 1970

| | Located In: | • | 93 DEC 29 PM 2: 59 | |
|--|------------------------------------|----------------|---|--|
| OGEMAW (County) | | Corner Code ## | | |
| Public Land Survey | T _21N_ R _3E T R T R T R | M-1 | Winds Yough. REGISTER OF DEEDS OBEHAN COUNTY | |
| 2. Property Controlling in Section | | | Oddina Gog.H (| |
| Miscellaneous Property in Sec. | S T R S T R | | Register of Deeds Stamp & File Number | |
| 4. Lot No | , Recorded Plat | | ABCDEFGHIJKL | |

TIMOTHY L. LAPHAM , in a field survey on November 19⁹3 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 10 12 13
- A. Description of original monument and accessories and/or subsequent restoration:
- M-1: 1838 L. CLASON; POST; TAMARACK 12" N67-1/2W 85LK; S. MAPLE 16" S49W 164 LK; B. OAK 14" N52-1/2E 64 LK; S. MAPLE 10" S53E 60 LK 8/13/1971 CALDWELL SURVEY 1-76; DISTANCE NORTH 8/1971 CALDWELL LCRC 1-19; CORNER AND WITNESSES 1978+/- COUNTY ROAD PLANS; CORNER AND WITNESSES 3/3/1989 LEDY LCRC 2-85; RESET CORNER AND WITNESSES
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- M-1: FOUND RAILROAD SPIKE PER 1989 LCRC FOUND RECORD WITNESSES:

NE 101.4' 6" ASH

NNW 139.25' PK IN POWER POLE

ESE 108.67' SPIKE IN OAK

DISTANCE TO NORTH MATCHES 1971 SURVEY

THIS CORNER ESTABLISHED IN OGEMAW COUNTY REMONUMENTATION PROGRAM. SEE DOSSIER FOR DETAILED REPORT.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- M-1: SET 5/8"X36" REROD WITH 3" OGEMAW COUNTY MONUMENT CAP IN MON. BOX

AZ 32° 101.43' SPIKE IN SE FACE 8" ASH AZ 343° 139.28' PK NAIL IN NE FACE UTILITY POLE

AZ 101° 108.69' SPIKE IN S FACE 13" TWIN OAK

AZ 50° 50.90' SPIKE IN SE FACE UTILITY POLE

AZ 45° 47.29' CAPPED IRON (LEDY) AZ 136° 46.79' CAPPED IRON (LAPHAM)

AZ 230° 58.98 SPIKE IN SE FACE UTILITY POLE

SE HAM 27595 POFESSION

Surveyor's Michigan License No. -27595

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28 REVISED MAY 14

REVISED JAN